DATE: 25/11/2017

MOM

1. Clamping two hand operation (Switch the place of Valve)
2. Rotation Two handed operation (place a new valve)
3. Pressure Control Valve for rotation movement.
4. Bearing cover to be place (small plate to be placed)
5. Tube- Festo (Approval after the NIHVA only need to discuss)
6. Guard to extend for rack & Pinion arrangement
7. Properly Routing of all tubes as discussed.

- NOTE: AFTER ABOVE POINTS CLEAR WE WILL DISPATCH THE MATERIAL

  CLIENT NEED TO KEEP 12*7 METER AREA OPEN FOR THE INSTALLATION AS PER DAP & DICUSSED

Mayur Derle
25/11/17
NIHVA Technologies
Pune

Suresh S
25-11-17
Tenneco, Chennai

Rajendra Gole
25-11-17
Tenneco,

Office Add:- 187/ G-Block, 1st Floor, Thermax Chowk, MIDC, Above Renault Showroom, Chinchwad, Pune - 411019
Reg. Add:- 8/1 Coromant Heg. Soc. Sec. No. 27, Nigdi, Pradhikaran, Pune - 411044.
+91 2066 3040 33 +91 85 51091 333 sales@nihva.com www.nihva.com | CIN No U72900PN2012PTC143948