Gmail

NIHVA Design <design2@nihva.com>

Request to provide weight estimation - SCON

11 messages

Information NIHVA <information@nihva.com> Thu, Jun 26, 2025 at 10:10 AM
To: NIHVA Design <Design2@nihva.com>, Automation Solution <designtech@nihva.com>, design1@nihva.com
Cc: Support NIHVA <support@nihva.com>, sales@nihva.com, info@nihva.com, nihvacare@nihva.com

Dear Design Team,

Please find the details in table below. Kindly review it and provide the weight estimation at your earliest convenience.

SL.NO.	DESCRIPTION
18.2	Supplying and fixing of Motorized MS Telescopic Gate CE Certified As Per European Standard Gate drawing as per Architectural intent, Single Side- 3 Leaf, Surface Finish- PU Paint, Automation System Push Button- 1 No. Technical Specification as mention below:- Gate Frame- MS Rectangular Tubes (W) 100 x (H) 50 x (Thk) 3.2mm thick Internal Members- Horizontal Member-MS Round Bars (Día) 5 x (Día) 5 x (L) 3.05 mm With Gap Centre To Centre 600mm & Vertical Member-MS Rectangular Tubes (W) 50 x (H) 25 x (Thk) 4 mm With Gap Centre To Centre 75mm Full Height Column- MS Rectangular Tubes (W) 100 x (H) 50 x (Thk) 3.2 mm Bottom Rail- Single Track-Polished Bright bar 20 mm dia rail welded over Bottom I-Beam-ISMB 100 x 50 Bottom Roller- Single Track-Heavy Duty bottom rollers with dual bearing mechanism for free sliding movement fixed at the bottom member of gate frame. Drive- (1) Imported Make Electric motor , (2) Power Supply Single/Three Phase 50/60 Hz, (3) Inbuilt magnetic Limit switch , (4) Inbuilt control panel, (5) Protection class IP 54, (6) CE Certified Emergency Operation - Rotating release device easy to operate & key protected (Standard) Push Button- From Inside on Full Height Column (Optional: placement of push button as per client requirement). Surface Finish- epoxy primer & P U Paint of approved color as per EIC, Standard Accessories- additional Flashing Lamp with Alarm Extra Push Button vertical Safety Edge Sensor Size- w)9.15m X (h)1.8m-1 Nos

18.2.2	Manual swing type wicket gate
	PU Paint
	Wicket gate/Side Gate (w) 1.5 m X (h) 1.8 m-1 Nos

With Best Regards,

Yadnya Girme

+91- 8530872333

NIHVA Design <Design2@nihva.com> Thu, Jun 26, 2025 at 12:45 PM
To: Nihva Design <nihva.design1@gmail.com>, design.nihva@gamail.com

[Quoted text hidden]

NIHVA Design <Design2@nihva.com> Thu, Jun 26, 2025 at 4:10 PM
To: Nihva Design <nihva.design1@gmail.com>, design.nihva@gamail.com

Dear Team,

This is final wtg estimation .

Regards,
Vivek Bhosale
[Quoted text hidden]

Weight Estimation -SCON.xlsx
223K

NIHVA Design <Design2@nihva.com> Thu, Jun 26, 2025 at 5:43 PM
To: Information NIHVA <information@nihva.com>
Cc: Automation Solution <designtech@nihva.com>, design1@nihva.com, Support NIHVA <support@nihva.com>, sales@nihva.com, info@nihva.com, nihvacare@nihva.com

Dear Team,

I am sending Final wtg estimation.(it is revised wtg estimation)
Please consider this one.

Regards,
Bharati Sabale
[Quoted text hidden]

Weight Estimation -SCON.xlsx
223K

Mail Delivery Subsystem <mailer-daemon@googlemail.com> Thu, Jun 26, 2025 at 5:43 PM
To: design2@nihva.com

Address not found

Your message wasn't delivered to **design1@nihva.com** because the address couldn't be found, or is unable to receive mail.

LEARN MORE

The response was:

```
550 5.1.1 The email account that you tried to reach does not exist. Please try double-checking the recipient's email
address for typos or unnecessary spaces. For more information, go to https://support.google.com/mail/?p=NoSuchUser
98e67ed59e1d1-3159dfbd461sor11963749a91.2 - gsmtp
```

Final-Recipient: rfc822; design1@nihva.com
Action: failed
Status: 5.1.1
Diagnostic-Code: smtp; 550-5.1.1 The email account that you tried to reach does not exist. Please try
550-5.1.1 double-checking the recipient's email address for typos or
550-5.1.1 unnecessary spaces. For more information, go to
550 5.1.1 https://support.google.com/mail/?p=NoSuchUser 98e67ed59e1d1-3159dfbd461sor11963749a91.2 - gsmtp
Last-Attempt-Date: Thu, 26 Jun 2025 05:13:09 -0700 (PDT)

noname
3K

Mail Delivery Subsystem <mailer-daemon@googlemail.com> Fri, Jun 27, 2025 at 1:38 PM
To: design2@nihva.com



Delivery incomplete

There was a temporary problem delivering your message to **design.nihva@gamail.com**. Gmail will retry for 47 more hours. You'll be notified if the delivery fails permanently.

The response was:

```
DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR DNS type 'aaaa' lookup of localhost. responded
with code NXDOMAIN DNS type 'a' lookup of localhost. responded with code NXDOMAIN
```

Final-Recipient: rfc822; design.nihva@gamail.com
Action: delayed
Status: 4.4.3
Diagnostic-Code: smtp; DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR
DNS type 'aaaa' lookup of localhost. responded with code NXDOMAIN
DNS type 'a' lookup of localhost. responded with code NXDOMAIN
Last-Attempt-Date: Fri, 27 Jun 2025 01:08:47 -0700 (PDT)
Will-Retry-Until: Sun, 29 Jun 2025 00:14:45 -0700 (PDT)

noname
3K

Mail Delivery Subsystem <mailer-daemon@googlemail.com> Fri, Jun 27, 2025 at 4:39 PM
To: design2@nihva.com

[Quoted text hidden]

Final-Recipient: rfc822; design.nihva@gamail.com
Action: delayed
Status: 4.4.3
Diagnostic-Code: smtp; DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR
DNS type 'aaaa' lookup of localhost. responded with code NXDOMAIN
DNS type 'a' lookup of localhost. responded with code NXDOMAIN
Last-Attempt-Date: Fri, 27 Jun 2025 04:09:29 -0700 (PDT)
Will-Retry-Until: Sun, 29 Jun 2025 03:39:42 -0700 (PDT)

noname
3K

Mail Delivery Subsystem <mailer-daemon@googlemail.com> Sat, Jun 28, 2025 at 1:42 PM
To: design2@nihva.com

Delivery incomplete

There was a temporary problem delivering your message to **design.nihva@gamail.com**. Gmail will retry for 23 more hours. You'll be notified if the delivery fails permanently.

The response was:

```
DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR DNS type 'aaaa' lookup of localhost. responded
with code NXDOMAIN DNS type 'a' lookup of localhost. responded with code NXDOMAIN
```

Final-Recipient: rfc822; design.nihva@gamail.com
Action: delayed
Status: 4.4.3
Diagnostic-Code: smtp; DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR
DNS type 'aaaa' lookup of localhost. responded with code NXDOMAIN
DNS type 'a' lookup of localhost. responded with code NXDOMAIN
Last-Attempt-Date: Sat, 28 Jun 2025 01:12:21 -0700 (PDT)
Will-Retry-Until: Sun, 29 Jun 2025 00:14:45 -0700 (PDT)

noname
3K

Mail Delivery Subsystem <mailer-daemon@googlemail.com> Sat, Jun 28, 2025 at 5:54 PM
To: design2@nihva.com

Delivery incomplete

There was a temporary problem delivering your message to **design.nihva@gamail.com**. Gmail will retry for 22 more hours. You'll be notified if the delivery fails permanently.

The response was:

```
DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR DNS type 'aaaa' lookup of localhost. responded
with code NXDOMAIN DNS type 'a' lookup of localhost. responded with code NXDOMAIN
```

Final-Recipient: rfc822; design.nihva@gamail.com
Action: delayed
Status: 4.4.3
Diagnostic-Code: smtp; DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR
DNS type 'aaaa' lookup of localhost. responded with code NXDOMAIN
DNS type 'a' lookup of localhost. responded with code NXDOMAIN
Last-Attempt-Date: Sat, 28 Jun 2025 05:24:42 -0700 (PDT)
Will-Retry-Until: Sun, 29 Jun 2025 03:39:42 -0700 (PDT)

noname
3K

Mail Delivery Subsystem <mailer-daemon@googlemail.com> Sun, Jun 29, 2025 at 5:15 PM
To: design2@nihva.com

Message not delivered

There was a problem delivering your message to **design.nihva@gamail.com**. See the technical details below.

The response was:

```
DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR DNS type 'aaaa' lookup of localhost. responded with code NXDOMAIN DNS type 'a' lookup of localhost. responded with code NXDOMAIN
```

Final-Recipient: rfc822; design.nihva@gamail.com
Action: failed
Status: 4.4.3
Diagnostic-Code: smtp; DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR
DNS type 'aaaa' lookup of localhost. responded with code NXDOMAIN
DNS type 'a' lookup of localhost. responded with code NXDOMAIN
Last-Attempt-Date: Sun, 29 Jun 2025 04:45:46 -0700 (PDT)

noname
3K

Mail Delivery Subsystem <mailer-daemon@googlemail.com> Sun, Jun 29, 2025 at 7:49 PM
To: design2@nihva.com

[Quoted text hidden]

Final-Recipient: rfc822; design.nihva@gamail.com
Action: failed
Status: 4.4.3
Diagnostic-Code: smtp; DNS Error: DNS type 'mx' lookup of gamail.com responded with code NOERROR
DNS type 'aaaa' lookup of localhost. responded with code NXDOMAIN
DNS type 'a' lookup of localhost. responded with code NXDOMAIN
Last-Attempt-Date: Sun, 29 Jun 2025 07:19:33 -0700 (PDT)

noname
3K