CN-TFD airframe logbook: entries from 1 January 2024 to 26 October 2026 (printed extract)

Date	Airframe hours	Work order	Entry	Signed
2024-01-14	8,937.1	WO-2024-0022	Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D. Replaced right main tire. Replaced all eight spark plugs. Oil and filter changed.	K. Bennani, MA-B1-0212
2024-02-20	9,026.7	WO-2024-0079	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Adjusted alternator belt tension per maintenance manual. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-03-12	9,077.6	WO-2024-0114	Shimmy damper worn. Replaced shimmy damper; nose gear torque links checked for free play.	A. Tazi, MA-B1-0457
2024-03-30	9,121.2	WO-2024-0142	100-hour inspection per 14 CFR 91.409(b). Replaced exhaust gasket at cylinder 3. Replaced left cabin door seal. Replaced left brake linings. Oil and filter changed.	A. Tazi, MA-B1-0457
2024-05-09	9,218.2	WO-2024-0203	100-hour inspection per 14 CFR 91.409(b). Removed corrosion, treated and painted battery box; neutralized battery area. Replaced trim tab actuator rod end bearings; free play within limits. Replaced right main tire. Oil and filter changed.	A. Tazi, MA-B1-0457
2024-06-17	9,312.7	WO-2024-0262	100-hour inspection per 14 CFR 91.409(b). Cleaned, gapped, and rotated all eight spark plugs. Replaced left main tire. Oil and filter changed.	K. Bennani, MA-B1-0212
2024-07-24	9,402.3	WO-2024-0321	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Adjusted alternator belt tension per maintenance manual. Replaced all eight spark plugs. Oil and filter changed.	K. Bennani, MA-B1-0212
2024-09-02	9,499.2	WO-2024-0381	100-hour inspection per 14 CFR 91.409(b). Replaced trim tab actuator rod end bearings; free play within limits. Oil and filter changed.	K. Bennani, MA-B1-0212
2024-10-10	9,591.3	WO-2024-0442	100-hour inspection per 14 CFR 91.409(b). Removed corrosion, treated and painted battery box; neutralized battery area. Serviced nose strut with hydraulic fluid and air. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-11-17	9,683.4	WO-2024-0500	100-hour inspection per 14 CFR 91.409(b). Replaced left cabin door seal. Cleaned, gapped, and rotated all eight spark plugs. Replaced left main tire. Oil and filter changed.	A. Tazi, MA-B1-0457
2024-12-25	9,775.4	WO-2024-0560	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Oil and filter changed.	K. Bennani, MA-B1-0212
2025-01-23	9,845.7	WO-2025-0034	Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D. Replaced right main tire. Replaced all eight spark plugs. Oil and filter changed.	K. Bennani, MA-B1-0212
2025-03-03	9,940.2	WO-2025-0094	100-hour inspection per 14 CFR 91.409(b). Adjusted alternator belt tension per maintenance manual. Oil and filter changed.	A. Tazi, MA-B1-0457

Date	Airframe hours	Work order	Entry	Signed
2025-03-03	9,940.2	WO-2025-0095	Replaced engine oil pressure switch with new, zero-time switch P/N 83278, per AD 2013-11-11. Removed switch P/N 83278 at 2,951.3 hours since installation. Ground run: oil pressure indication normal, no leaks. Torque per maintenance manual. Wrench T-037.	A. Tazi, MA-B1-0457
2025-04-03	10,039.4	WO-2025-0142	100-hour inspection per 14 CFR 91.409(b). Replaced left brake linings. Oil and filter changed.	R. El Fassi, MA-B1-0618
2025-05-02	10,132.1	WO-2025-0185	100-hour inspection per 14 CFR 91.409(b). Replaced trim tab actuator rod end bearings; free play within limits. Serviced nose strut with hydraulic fluid and air. Oil and filter changed.	K. Bennani, MA-B1-0212
2025-05-20	10,189.7	WO-2025-0210	Replaced rocker cover gasket, cylinder 2. Torque per maintenance manual. Wrench T-031.	K. Bennani, MA-B1-0212
2025-05-31	10,224.9	WO-2025-0227	100-hour inspection per 14 CFR 91.409(b). Replaced left cabin door seal. Replaced exhaust gasket at cylinder 3. Removed corrosion, treated and painted battery box; neutralized battery area. Oil and filter changed.	A. Tazi, MA-B1-0457
2025-06-29	10,317.7	WO-2025-0273	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Replaced all eight spark plugs. Replaced right main tire. Oil and filter changed.	K. Bennani, MA-B1-0212
2025-07-28	10,410.4	WO-2025-0316	100-hour inspection per 14 CFR 91.409(b). Oil and filter changed.	R. El Fassi, MA-B1-0618
2025-08-25	10,500.0	WO-2025-0358	100-hour inspection per 14 CFR 91.409(b). Oil and filter changed.	A. Tazi, MA-B1-0457
2025-08-25	10,500.0	WO-2025-0359	Removed engine for overhaul. Engine sent to Souss Engine Overhaul, Agadir. Reinstalled the overhauled engine, same serial number. Engine time since overhaul reset to 0.0. Ground run and leak check satisfactory. Engine logbook updated.	R. El Fassi, MA-B1-0618
2025-09-22	10,589.9	WO-2025-0399	100-hour inspection per 14 CFR 91.409(b). Oil and filter changed.	A. Tazi, MA-B1-0457
2025-10-21	10,682.9	WO-2025-0442	100-hour inspection per 14 CFR 91.409(b). Serviced nose strut with hydraulic fluid and air. Oil and filter changed.	K. Bennani, MA-B1-0212
2025-11-04	10,727.9	WO-2025-0464	Static system test and altimeter test per 14 CFR 91.411 and Part 43 Appendix E. Transponder test per 14 CFR 91.413 and Part 43 Appendix F. All tests within limits. Next tests due within 24 calendar months.	K. Bennani, MA-B1-0212
2025-11-20	10,779.2	WO-2025-0488	100-hour inspection per 14 CFR 91.409(b). Replaced left brake linings. Oil and filter changed.	K. Bennani, MA-B1-0212
2025-12-09	10,840.2	WO-2025-0514	Installed new static wick.	K. Bennani, MA-B1-0212

Date	Airframe hours	Work order	Entry	Signed
2025-12-20	10,875.5	WO-2025-0532	100-hour inspection per 14 CFR 91.409(b). Adjusted alternator belt tension per maintenance manual. Replaced exhaust gasket at cylinder 3. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-01-15	10,958.9	WO-2026-0021	Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D. Cleaned, gapped, and rotated all eight spark plugs. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-02-13	11,052.0	WO-2026-0061	100-hour inspection per 14 CFR 91.409(b). Replaced all eight spark plugs. Replaced trim tab actuator rod end bearings; free play within limits. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-03-13	11,141.9	WO-2026-0099	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Replaced left cabin door seal. Oil and filter changed.	R. El Fassi, MA-B1-0618
2026-04-13	11,241.4	WO-2026-0140	100-hour inspection per 14 CFR 91.409(b). Replaced right main tire. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-05-12	11,334.4	WO-2026-0182	100-hour inspection per 14 CFR 91.409(b). Removed corrosion, treated and painted battery box; neutralized battery area. Adjusted alternator belt tension per maintenance manual. Oil and filter changed.	K. Bennani, MA-B1-0212
2026-06-09	11,424.3	WO-2026-0219	100-hour inspection per 14 CFR 91.409(b). Serviced nose strut with hydraulic fluid and air. Replaced left brake linings. Replaced exhaust gasket at cylinder 3. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-07-07	11,514.2	WO-2026-0256	100-hour inspection per 14 CFR 91.409(b). Oil and filter changed.	K. Bennani, MA-B1-0212
2026-08-05	11,607.2	WO-2026-0297	100-hour inspection per 14 CFR 91.409(b). Oil and filter changed.	R. El Fassi, MA-B1-0618
2026-09-02	11,697.1	WO-2026-0335	100-hour inspection per 14 CFR 91.409(b). Cleaned, gapped, and rotated all eight spark plugs. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-09-08	11,716.4	WO-2026-0341	Right fuel cap gasket cracked. Replaced gasket; drained sumps until clear.	R. El Fassi, MA-B1-0618
2026-10-01	11,790.2	WO-2026-0374	100-hour inspection per 14 CFR 91.409(b). Replaced all eight spark plugs. Replaced right main tire. Replaced trim tab actuator rod end bearings; free play within limits. Oil and filter changed.	R. El Fassi, MA-B1-0618