CN-TFG airframe logbook: entries from 1 January 2024 to 26 October 2026 (printed extract)

Date	Airframe hours	Work order	Entry	Signed
2024-01-22	13,523.9	WO-2024-0036	100-hour inspection per 14 CFR 91.409(b). Replaced right main tire. Replaced left main tire. Serviced nose strut with hydraulic fluid and air. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-03-26	13,615.1	WO-2024-0136	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Replaced left brake linings. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-05-30	13,707.6	WO-2024-0235	100-hour inspection per 14 CFR 91.409(b). Removed corrosion, treated and painted battery box; neutralized battery area. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-07-07	13,761.8	WO-2024-0295	Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D. Replaced trim tab actuator rod end bearings; free play within limits. Replaced left cabin door seal. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-08-27	13,834.4	WO-2024-0372	Replaced FADEC backup battery per AD 2011-06-02. Battery test satisfactory. Next replacement due within 12 calendar months.	R. El Fassi, MA-B1-0618
2024-09-14	13,860.0	WO-2024-0401	100-hour inspection per 14 CFR 91.409(b). Replaced right main tire. Oil and filter changed.	R. El Fassi, MA-B1-0618
2024-10-08	13,894.2	WO-2024-0439	Static system test and altimeter test per 14 CFR 91.411 and Part 43 Appendix E. Transponder test per 14 CFR 91.413 and Part 43 Appendix F. All tests within limits. Next tests due within 24 calendar months.	R. El Fassi, MA-B1-0618
2024-11-05	13,934.1	WO-2024-0482	Downloaded FADEC data: intermittent signal from rail pressure sensor B. Cleaned and secured connector. FADEC test passed. Data sent to Technify.	R. El Fassi, MA-B1-0618
2024-11-20	13,955.5	WO-2024-0506	100-hour inspection per 14 CFR 91.409(b). Replaced left main tire. Serviced nose strut with hydraulic fluid and air. Oil and filter changed.	R. El Fassi, MA-B1-0618
2025-01-24	14,048.0	WO-2025-0038	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Oil and filter changed.	A. Tazi, MA-B1-0457
2025-03-26	14,134.9	WO-2025-0130	Found a seep at the gearbox drain plug. Replaced sealing ring; topped up gearbox oil. Leak check satisfactory.	R. El Fassi, MA-B1-0618
2025-04-01	14,143.5	WO-2025-0137	100-hour inspection per 14 CFR 91.409(b). Oil and filter changed.	R. El Fassi, MA-B1-0618
2025-06-04	14,234.6	WO-2025-0232	100-hour inspection per 14 CFR 91.409(b). Removed corrosion, treated and painted battery box; neutralized battery area. Oil and filter changed.	A. Tazi, MA-B1-0457

Date	Airframe hours	Work order	Entry	Signed
2025-07-13	14,290.2	WO-2025-0293	Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D. Replaced trim tab actuator rod end bearings; free play within limits. Oil and filter changed.	A. Tazi, MA-B1-0457
2025-08-19	14,342.9	WO-2025-0346	Replaced FADEC backup battery per AD 2011-06-02. Battery test satisfactory. Next replacement due within 12 calendar months.	R. El Fassi, MA-B1-0618
2025-08-24	14,350.0	WO-2025-0356	Removed engine for overhaul. Engine sent to the Technify factory for overhaul. Reinstalled the overhauled engine, same serial number. Engine time since overhaul reset to 0.0. Ground run and leak check satisfactory. Engine logbook updated.	R. El Fassi, MA-B1-0618
2025-09-15	14,381.4	WO-2025-0389	100-hour inspection per 14 CFR 91.409(b). Replaced left cabin door seal. Oil and filter changed.	A. Tazi, MA-B1-0457
2025-11-23	14,479.7	WO-2025-0490	100-hour inspection per 14 CFR 91.409(b). Replaced left brake linings. Oil and filter changed.	K. Bennani, MA-B1-0212
2026-01-27	14,572.4	WO-2026-0039	100-hour inspection per 14 CFR 91.409(b). Replaced left main tire. Replaced right main tire. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-04-01	14,663.7	WO-2026-0126	100-hour inspection per 14 CFR 91.409(b). Replaced induction air filter. Oil and filter changed.	K. Bennani, MA-B1-0212
2026-06-02	14,752.0	WO-2026-0208	Induction air filter partly blocked by debris. Replaced air filter. Load check satisfactory.	K. Bennani, MA-B1-0212
2026-06-07	14,759.2	WO-2026-0215	100-hour inspection per 14 CFR 91.409(b). Removed corrosion, treated and painted battery box; neutralized battery area. Serviced nose strut with hydraulic fluid and air. Oil and filter changed.	A. Tazi, MA-B1-0457
2026-07-25	14,827.6	WO-2026-0282	Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D. Replaced trim tab actuator rod end bearings; free play within limits. Replaced left cabin door seal. Oil and filter changed.	K. Bennani, MA-B1-0212
2026-08-11	14,851.8	WO-2026-0304	Replaced FADEC backup battery per AD 2011-06-02. Battery test satisfactory. Next replacement due within 12 calendar months.	R. El Fassi, MA-B1-0618
2026-09-30	14,923.1	WO-2026-0371	100-hour inspection per 14 CFR 91.409(b). Replaced left main tire. Replaced left brake linings. Oil and filter changed.	K. Bennani, MA-B1-0212