Anfa Aero Services: work order WO-2024-0091

Field	Value
Date completed	28 February 2024
Registration	CN-TFA
Aircraft	Cessna 172S
Serial number	172S9488
Airframe total time at completion (h)	7,252.0
Station	Casablanca

Request

Annual inspection.

Work performed

1. Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D, using the Cessna 172 inspection checklist.

2. ELT inspected per 14 CFR 91.207(d): installation, battery date, operation, and radiated signal.

3. Changed engine oil and filter. Compression check, cylinders 1 to 4: 78/80, 72/80, 74/80, 75/80.

4. Discrepancy: Alternator belt tension low. Corrective action: Adjusted alternator belt tension per maintenance manual.

5. Discrepancy: Left brake linings at minimum thickness. Corrective action: Replaced left brake linings.

6. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: Y. Alaoui

Return to service: R. El Fassi, licence MA-B1-0618