Anfa Aero Services: work order WO-2024-0142

Field	Value
Date completed	30 March 2024
Registration	CN-TFD
Aircraft	Cessna 172R
Serial number	17281201
Airframe total time at completion (h)	9,121.2
Station	Casablanca

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.

2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 77/80, 75/80, 71/80, 76/80.

3. Discrepancy: Exhaust gasket leaking at cylinder 3. Corrective action: Replaced exhaust gasket at cylinder 3.

4. Discrepancy: Left cabin door seal torn. Corrective action: Replaced left cabin door seal.

5. Discrepancy: Left brake linings at minimum thickness. Corrective action: Replaced left brake linings.

6. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: H. Ouazzani

Return to service: A. Tazi, licence MA-B1-0457