Anfa Aero Services: work order WO-2024-0231

Field	Value
Date completed	28 May 2024
Registration	CN-TFE
Aircraft	Cessna 172R
Serial number	17280744
Airframe total time at completion (h)	12,177.5
Station	Casablanca

Request

Autopilot disconnects in turbulence.

Work performed

1. Found a loose pin in the KAP 140 roll servo connector. Repaired connector.
2. Ground test of the autopilot satisfactory.

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: N. Berrada

Return to service: K. Bennani, licence MA-B1-0212