Anfa Aero Services: work order WO-2024-0260

Field	Value
Date completed	16 June 2024
Registration	CN-TFB
Aircraft	Cessna 172S
Serial number	172S10237
Airframe total time at completion (h)	6,701.2
Station	Casablanca

Request

Annual inspection.

Work performed

1. Annual inspection per 14 CFR 91.409(a) and the scope and detail of 14 CFR Part 43 Appendix D, using the Cessna 172 inspection checklist.

2. ELT inspected per 14 CFR 91.207(d): installation, battery date, operation, and radiated signal.

3. Changed engine oil and filter. Compression check, cylinders 1 to 4: 72/80, 71/80, 71/80, 73/80.

4. Discrepancy: Elevator trim tab free play at the limit. Corrective action: Replaced trim tab actuator rod end bearings; free play within limits.

5. Discrepancy: Spark plugs worn beyond limits. Corrective action: Replaced all eight spark plugs.

6. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	
REM37BY	Spark plug	8	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: M. Chraibi

Return to service: K. Bennani, licence MA-B1-0212