Anfa Aero Services: work order WO-2024-0491

Field	Value
Date completed	11 November 2024
Registration	CN-TFF
Aircraft	Cessna 172S
Serial number	172S11845
Airframe total time at completion (h)	3,262.1
Station	Beni Mellal

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.

2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 78/80, 77/80, 74/80, 71/80.

3. Discrepancy: Exhaust gasket leaking at cylinder 3. Corrective action: Replaced exhaust gasket at cylinder 3.

4. Discrepancy: Left brake linings at minimum thickness. Corrective action: Replaced left brake linings.

5. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: N. Berrada

Return to service: K. Bennani, licence MA-B1-0212