# Anfa Aero Services: work order WO-2024-0535

| Field | Value |
|---|---|
| Date completed | 10 December 2024 |
| Registration | CN-TFA |
| Aircraft | Cessna 172S |
| Serial number | 172S9488 |
| Airframe total time at completion (h) | 8,101.8 |
| Station | Casablanca |

## *Request*

100-hour inspection.

## *Work performed*

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.

2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 72/80, 70/80, 72/80, 70/80.

3. Discrepancy: Spark plugs eroded. Corrective action: Cleaned, gapped, and rotated all eight spark plugs.

4. Discrepancy: Exhaust gasket leaking at cylinder 3. Corrective action: Replaced exhaust gasket at cylinder 3.

5. Discrepancy: Elevator trim tab free play at the limit. Corrective action: Replaced trim tab actuator rod end bearings; free play within limits.

6. Aircraft found airworthy after correction of the discrepancies listed.

## *Parts used*

| Part number | Description | Quantity | Serial number |
|---|---|---|---|
| CH48110-1 | Oil filter | 1 | |

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: Y. Alaoui

Return to service: K. Bennani, licence MA-B1-0212