Anfa Aero Services: work order WO-2024-0549

Field	Value
Date completed	19 December 2024
Registration	CN-TFC
Aircraft	Cessna 172S
Serial number	172S11290
Airframe total time at completion (h)	4,871.0
Station	Beni Mellal

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.
2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 71/80, 75/80, 70/80, 78/80.
3. Discrepancy: Left brake linings at minimum thickness. Corrective action: Replaced left brake linings.
4. Discrepancy: Left cabin door seal torn. Corrective action: Replaced left cabin door seal.
5. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: Y. Alaoui

Return to service: K. Bennani, licence MA-B1-0212