# Anfa Aero Services: work order WO-2025-0056

| Field | Value |
|---|---|
| Date completed | 6 February 2025 |
| Registration | CN-TFC |
| Aircraft | Cessna 172S |
| Serial number | 172S11290 |
| Airframe total time at completion (h) | 4,969.1 |
| Station | Beni Mellal |

## *Request*

100-hour inspection.

## *Work performed*

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.

2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 77/80, 72/80, 74/80, 78/80.

3. Discrepancy: Spark plugs eroded. Corrective action: Cleaned, gapped, and rotated all eight spark plugs.

4. Discrepancy: Alternator belt tension low. Corrective action: Adjusted alternator belt tension per maintenance manual.

5. Aircraft found airworthy after correction of the discrepancies listed.

## *Parts used*

| Part number | Description | Quantity | Serial number |
|---|---|---|---|
| CH48110-1 | Oil filter | 1 | |

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: M. Chraibi

Return to service: A. Tazi, licence MA-B1-0457