Anfa Aero Services: work order WO-2025-0202

Field	Value
Date completed	13 May 2025
Registration	CN-TFA
Aircraft	Cessna 172S
Serial number	172S9488
Airframe total time at completion (h)	8,559.5
Station	Casablanca

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.

2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 78/80, 78/80, 77/80, 74/80.

3. Discrepancy: Exhaust gasket leaking at cylinder 3. Corrective action: Replaced exhaust gasket at cylinder 3.

4. Discrepancy: Alternator belt tension low. Corrective action: Adjusted alternator belt tension per maintenance manual.

5. Discrepancy: Corrosion on battery box. Corrective action: Removed corrosion, treated and painted battery box; neutralized battery area.

6. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: Y. Alaoui

Return to service: K. Bennani, licence MA-B1-0212