Anfa Aero Services: work order WO-2025-0384

Field	Value
Date completed	13 September 2025
Registration	CN-TFB
Aircraft	Cessna 172S
Serial number	172S10237
Airframe total time at completion (h)	7,624.0
Station	Casablanca

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.

2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 74/80, 76/80, 75/80, 72/80.

3. Discrepancy: Alternator belt tension low. Corrective action: Adjusted alternator belt tension per maintenance manual.

4. Discrepancy: Spark plugs eroded. Corrective action: Cleaned, gapped, and rotated all eight spark plugs.

5. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: S. Idrissi

Return to service: A. Tazi, licence MA-B1-0457