Anfa Aero Services: work order WO-2025-0524

Field	Value
Date completed	14 December 2025
Registration	CN-TFB
Aircraft	Cessna 172S
Serial number	172S10237
Airframe total time at completion (h)	7,811.0
Station	Casablanca

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.
2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 70/80, 72/80, 73/80, 72/80.
3. Discrepancy: Left brake linings at minimum thickness. Corrective action: Replaced left brake linings.
4. Discrepancy: Right main tire worn to the wear limit. Corrective action: Replaced right main tire.
5. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	
6.00-6-6PLY	Main wheel tire	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: M. Chraibi

Return to service: A. Tazi, licence MA-B1-0457