Anfa Aero Services: work order WO-2026-0042

Field	Value
Date completed	31 January 2026
Registration	CN-TFC
Aircraft	Cessna 172S
Serial number	172S11290
Airframe total time at completion (h)	5,688.2
Station	Beni Mellal

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.

2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 78/80, 72/80, 71/80, 76/80.

3. Discrepancy: Elevator trim tab free play at the limit. Corrective action: Replaced trim tab actuator rod end bearings; free play within limits.

4. Discrepancy: Left brake linings at minimum thickness. Corrective action: Replaced left brake linings.

5. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: H. Ouazzani

Return to service: R. El Fassi, licence MA-B1-0618