Anfa Aero Services: work order WO-2026-0146

Field	Value
Date completed	16 April 2026
Registration	CN-TFB
Aircraft	Cessna 172S
Serial number	172S10237
Airframe total time at completion (h)	8,061.2
Station	Casablanca

Request

Oil seep at oil cooler hose after engine reinstallation.

Work performed

1. Tightened oil cooler hose fitting. Torque per maintenance manual. Wrench T-022. Leak check satisfactory.

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: Y. Alaoui

Return to service: K. Bennani, licence MA-B1-0212