Anfa Aero Services: work order WO-2026-0156

Field	Value
Date completed	23 April 2026
Registration	CN-TFA
Aircraft	Cessna 172S
Serial number	172S9488
Airframe total time at completion (h)	9,586.8
Station	Casablanca

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.
2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 77/80, 71/80, 74/80, 76/80.
3. Discrepancy: Left brake linings at minimum thickness. Corrective action: Replaced left brake linings.
4. Discrepancy: Induction air filter dirty. Corrective action: Replaced induction air filter.
5. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: S. Idrissi

Return to service: R. El Fassi, licence MA-B1-0618