Anfa Aero Services: work order WO-2026-0235

Field	Value
Date completed	22 June 2026
Registration	CN-TFC
Aircraft	Cessna 172S
Serial number	172S11290
Airframe total time at completion (h)	5,972.6
Station	Beni Mellal

Request

100-hour inspection.

Work performed

1. 100-hour inspection per 14 CFR 91.409(b), using the Cessna 172 inspection checklist.

2. Changed engine oil and filter. Compression check, cylinders 1 to 4: 71/80, 75/80, 75/80, 75/80.

3. Discrepancy: Induction air filter dirty. Corrective action: Replaced induction air filter.

4. Discrepancy: Alternator belt tension low. Corrective action: Adjusted alternator belt tension per maintenance manual.

5. Discrepancy: Corrosion on battery box. Corrective action: Removed corrosion, treated and painted battery box; neutralized battery area.

6. Aircraft found airworthy after correction of the discrepancies listed.

Parts used

Part number	Description	Quantity	Serial number
CH48110-1	Oil filter	1	

Certification: the work above was performed in accordance with 14 CFR Part 43 and the procedures manual. The aircraft is airworthy for the work performed.

Performed by: Y. Alaoui

Return to service: A. Tazi, licence MA-B1-0457