

R1: 1.00NC10H19 = > 0.600C2H4 + 0.600C3H6 + 0.500C3H5 - A + 0.500C4H71 - 3 + 0.500NC7H14

R2: 1.00NC10H19=>0.250C2H4+0.500C4H6+1.00NC5H11+0.500LC5H8

R3: 1.00NC10H20=>0.500C3H5-A+0.500C4H71-3+0.250NC5H11+0.750NC7H15