

- Pullups R2 and R3 may be unnecessary.
 R4,5,6 is a protection resistor and could be wired across instead...
- 5) Fuse (F1 or F2 footprint) could be wired across. T1K already has a fuse. More fuses never hurt.
- 6) C7 and C7_1 are optional and tie shields to GND



