



उत्तर प्रदेश  
Western Railway

**SABARMATI LOCO SHED**  
**MECHANICAL**  
**IC SCHEDULE FORM WAG-9HC**  
**UNDER FRAME SECTION**

Loco No.: 32456

Arr. Date: 05-08-25

Dep. Date: 11-08-25

Name of Supervisor: Sh. Kedar R. Vaghela - SSE Shift: 8/17 h

Name of Mechanic: Sh. Vikram Thakur - M-II<sup>nd</sup>

| Sr. No                   | DESCRIPTION (CBC schedule as per G-76)                                                                                                                            | CBC-1                 | CBC-2      | Checked by |
|--------------------------|-------------------------------------------------------------------------------------------------------------------------------------------------------------------|-----------------------|------------|------------|
| 1                        | CBC No. (Make & Yr)                                                                                                                                               | RTL                   | RTL        | Vikram     |
| 2                        | Check for any crack by MPT test of CBC Assly Items                                                                                                                | MPT Test by Lab -     |            | Taxan      |
|                          | CBC coupler body                                                                                                                                                  | Checked OK            | Checked OK | Vikram     |
|                          | Knuckle                                                                                                                                                           | 5.7.114<br>Checked OK | Checked OK |            |
|                          | Knuckle Pin (Dia new-41.28 mm, cond-38.00 mm)                                                                                                                     | 40.80                 | 40.80      |            |
|                          | Clevis                                                                                                                                                            | Checked OK            | Checked OK |            |
|                          | Clevis Pin (Dia new-38.00 mm, cond-36.00 mm)                                                                                                                      | 37.80                 | 37.60      |            |
| <b>Coupler Head</b>      |                                                                                                                                                                   |                       |            |            |
| 3                        | Check tell-tail of the coupler head after coupling                                                                                                                | Checked OK            | Checked OK |            |
| 4                        | Check cotter pin is installed.                                                                                                                                    | Checked OK            | Checked OK |            |
| 5                        | Visual check for external damage, condition of wear plate on shank. (Std-6.00 mm & Cond-1.00 mm)                                                                  | 5.25                  | 5.40       |            |
| 6                        | Check gap between coupler head and knuckle with condemning limit gauge. If wear out is not acceptable replace knuckle etc., as advised in the maintenance manual. | Checked OK            | Checked OK |            |
| 7                        | Check by inspector contour gauge (knuckle profile gauge, go gauge). Gauge no-2                                                                                    | Checked OK            | Checked OK |            |
| 8                        | Check wear & stretch of knuckle by using knuckle nose wear & stretch limit gauge Gauge no-3                                                                       | Checked OK            | Checked OK |            |
| 9                        | Check distortion of the coupler head by using aligning wing limit gauge                                                                                           | Checked OK            | Checked OK | Vikram     |
| 10                       | Checking wear & distortion of coupler head using vertical height aligning wing pocket & guard arm gauge (no-go gauge) Gauge no-1                                  | Checked OK            | Checked OK |            |
| 11                       | Checking vertical height alignment & guard arm of coupler in new condition using vertical height alignment wing pocket & guard arm gauge (go gauge) Gauge no-1    | Checked OK            | Checked OK |            |
| 12                       | Check working of CBC & Anti creep test                                                                                                                            | Checked OK            | Checked OK |            |
| 13                       | Check condition & proper working of CBC operating handle                                                                                                          | Checked OK            | Checked OK |            |
| 14                       | Check for any crack and damage in Yoke & draft gear                                                                                                               | Checked OK            | Checked OK |            |
| <b>Supporting device</b> |                                                                                                                                                                   |                       |            |            |
| 15                       | Visual check for external damage.                                                                                                                                 | Checked OK            | Checked OK |            |
| 16                       | Tighten the M16 nut & check height 165.0±1 mm both sides near the bolts.                                                                                          | Checked OK            | Checked OK |            |
| 17                       | Check free lateral movement of CBC shank.                                                                                                                         | Checked OK            | Checked OK |            |
| 18                       | Striker wear plate (new-8.00mm & Cond-2.00 mm)                                                                                                                    | 6.80                  | 7.00       |            |
| 19                       | CBC height (std-1105 mm & Min-1030 mm)                                                                                                                            | 1065                  | 1103       |            |

Check sheet for Transition screw coupling (MPMI No.25 Rev.00 RDSO Drg.No.SKDL-2894.)

| Sr. No | DESCRIPTION                                          | TSC-1           | TSC-2              | Checked by |
|--------|------------------------------------------------------|-----------------|--------------------|------------|
| 1      | screw coupling Make & Sr. No.                        | SKDL 2475 2/124 | SBTS 33 01 & S 120 | Vikram     |
| 2      | Check for any crackness by DPT/MPT test              | DPT / MPT       | by Lab -           | Taxan      |
| 3      | Checking for any damage of thread & operating handle | Checked OK      | Checked OK         | Vikram     |

|   |                                                                                                                               |                              |                              |                 |
|---|-------------------------------------------------------------------------------------------------------------------------------|------------------------------|------------------------------|-----------------|
| 4 | Checking of long & short shackle by Go-No go gauge (long Shackle New-43.0mm cond-39.5mm Short shackle New-28.0mm Cond-25.0mm) | Checked OK<br>43.50<br>27.60 | Checked OK<br>43.60<br>27.50 | } VBT<br>Vikram |
| 5 | Check for any damage of thread & operating handle of screw coupling                                                           | Checked OK                   | Checked OK                   |                 |
| 6 | Check the full operation of screw coupling                                                                                    | Checked OK                   | Checked OK                   |                 |
| 7 | Check condition of lock washer                                                                                                | Attached                     | Attached                     |                 |

### UST

| Sr. No | Axle Box Examination                                                                                                                                                  |               |                  |          |        |               |            |            |   |          | Checked by                                                                      |    |                       |  |
|--------|-----------------------------------------------------------------------------------------------------------------------------------------------------------------------|---------------|------------------|----------|--------|---------------|------------|------------|---|----------|---------------------------------------------------------------------------------|----|-----------------------|--|
| 1      | Remove earth cable.                                                                                                                                                   |               |                  |          |        |               |            |            |   |          |                                                                                 |    |                       |  |
|        | Axle box No.-1                                                                                                                                                        | Checked<br>OK | Axle box No.--6  |          |        | Checked<br>OK |            |            |   | CE-      | Vikram                                                                          |    |                       |  |
|        | Axle box No.--7                                                                                                                                                       |               | Axle box No.--12 |          |        |               | Checked OK |            |   | HE-      | Sanyar                                                                          |    |                       |  |
| 2      | Axle Box cover to remove.Remove lock ring .<br>Clean grease from surface.<br>Check any damaged/abnormality                                                            |               |                  |          |        |               |            |            |   |          | Removed<br>Cleaned<br>Checked OK                                                |    |                       |  |
| 3      | UST to check by Lab personel. C.E- PKB and HE- JSSmth                                                                                                                 |               |                  |          |        |               |            |            |   |          |                                                                                 |    |                       |  |
|        |                                                                                                                                                                       | 1             | 2                | 3        | 4      | 5             | 6          | 7          | 8 | 9        | 10                                                                              | 11 | 12                    |  |
|        | Axle no.                                                                                                                                                              | TG- 4622      | TG- 7024         | TG- 6624 |        | AG 5080       |            | TG 8124    |   | TG- 2222 |                                                                                 |    |                       |  |
|        | Brg. Make                                                                                                                                                             | -             | -                | -        |        | -             |            | -          |   | -        |                                                                                 |    |                       |  |
| 3 (A)  | Axle box old grease to remove fresh grease to fill, old grease sample to lab test for metal content.                                                                  |               |                  |          |        |               |            |            |   |          | Grease Removed<br>Sample by Lab -                                               |    | CE- PKB<br>HE- JSSmth |  |
| 3(B)   | 'O' ring to change                                                                                                                                                    |               |                  |          |        |               |            |            |   |          | Changed                                                                         |    |                       |  |
| 3(C)   | Axle box cover bolts M-16x45 to torque on 100 NM.                                                                                                                     |               |                  |          |        |               |            |            |   |          | All Bolt Torqued                                                                |    |                       |  |
|        | • Clamping plate bolts M-20x50 to torque on 330 NM                                                                                                                    |               |                  |          |        |               |            |            |   |          | All Bolt Torqued                                                                |    | CE- VBT               |  |
|        | • Inspection cover bolts M-12x35 to torqued on 85 NM                                                                                                                  |               |                  |          |        |               |            |            |   |          | All Bolt Torqued                                                                |    | Vikram                |  |
|        | • Erathing plate screw M-10x30 to torqued on 47 NM                                                                                                                    |               |                  |          |        |               |            |            |   |          | All Bolt Torqued                                                                |    |                       |  |
| 4      | Axle box greasing to do (as per SMI 246/TC 129 during UST)                                                                                                            |               |                  |          |        |               |            |            |   |          | Greasing done                                                                   |    | HE- Sanyar            |  |
| 5      | Insure all bolts of axle box back cover are tightened.                                                                                                                |               |                  |          |        |               |            |            |   |          | All Bolt Tighten                                                                |    | SK                    |  |
| 6      | Temp. 25°C above ambient while in HHP Amb.+56°C                                                                                                                       |               |                  |          |        |               |            |            |   |          | Checked OK                                                                      |    |                       |  |
| 7      | Greasing for axle box every 2.5 lakh KM or 18 month of service (As per TC-0034 Shell Gadus S5 V 42 p 2.5 to be use.)                                                  |               |                  |          |        |               |            |            |   |          | Shell Gadus S5 V 42 p 2.5 to be use.<br>Keg- Grease used                        |    |                       |  |
| 8      | MSU greasing<br>Clean Grease nipple.<br>Remove grease nipple<br>NDE Side Greasing to do .<br>(Servoplex- SHC120 as per SMI 307 Point no A(vii))<br>Fit Grease nipple. |               |                  |          |        |               |            |            |   |          | Clean<br>Remove<br>NDE Side Greasing<br>done. SHC<br>120 - 64 kg<br>Grease used |    | Amish<br>Amish        |  |
| 9      | Wheel distance to measure:-                                                                                                                                           |               |                  |          |        |               |            |            |   |          |                                                                                 |    |                       |  |
|        | Wheel No.                                                                                                                                                             | 1             | 2                | 3        | 4      | 5             | 6          | Checked by |   |          |                                                                                 |    |                       |  |
|        | Wheel Dist.                                                                                                                                                           | 159643        | 159633           | 159600   | 159600 | 159623        | 159616     | Sanyar     |   |          |                                                                                 |    |                       |  |

Any abnormality noticed during sch. and action taken

NIL

*[Signature]*

Sign of JE/SSE

VBT  
Sh. Vikram Thakur - M.T  
Sign of Tech

QAG - UF (Out of Course)

|                 |                                                                    |         |    |         |          |
|-----------------|--------------------------------------------------------------------|---------|----|---------|----------|
| Loco No. :-     | 32456                                                              | Sch. :- | IC | Date :- | 11-08-25 |
| Reason :-       | Dw to Gear Case No (5) One bolt Slak.                              |         |    |         |          |
|                 | Center/Pivot No (2) (3) Aclathan Ring gape less.                   |         |    |         |          |
| Action Taken :- | Gear Case No (5) One slak bolt in TM Attend by Elc. Staff          |         |    |         |          |
|                 | at Vahva. Same TM fitted, and other Gear Case Taken and Fitted and |         |    |         |          |
|                 | C/Pivot No. (2) (3) Aclathan Ring New Fitted.                      |         |    |         |          |



JE/SSE