



SABARMATI LOCO SHED
MECHANICAL
IC SCHEDULE FORM WAG-9HC
UNDER FRAME SECTION

Loco No.:- 32458 Arr. Date:- 21-10-2024 Dep. Date:- 22-10-2024
 Name of Supervisor:- S. Kalicharan - SSE Shift:- 8/12 H Name of Mechanic:- S. Sanyal Sinto - M-T St

Sr. No	DESCRIPTION (CBC schedule as per G-76)	CBC-1	CBC-2	Checked by
1	CBC No. (Make & Yr)	RTL 12/18	RTL 12/18	
2	Check for any crack by MPT test of CBC Assly Items	Checked MPT by Lab -	JS. Sinha	
	CBC coupler body	Checked OK	Checked OK	
	Knuckle	Checked OK	Checked OK	
	Knuckle Pin (Dia new-41.28 mm, cond-38.00 mm)	40.75	40.80	
	Clevis	Checked OK	Checked OK	
	Clevis Pin (Dia new-38.00 mm, cond-36.00 mm)	37.75	37.80	
Coupler Head				
3	Check tell-tail of the coupler head after coupling	Checked OK	Checked OK	
4	Check cotter pin is installed.	Checked OK	Checked OK	
5	Visual check for external damage, condition of wear plate on shank. (Std-6.00 mm & Cond-1.00 mm)	5.60	5.70	
6	Check gap between coupler head and knuckle with condemning limit gauge. If wear out is not acceptable replace knuckle etc., as advised in the maintenance manual.	Checked OK	Checked OK	porshu Rajesh
7	Check by inspector contour gauge (knuckle profile gauge, go gauge). Gauge no-2	Checked OK	Checked OK	
8	Check wear & stretch of knuckle by using knuckle nose wear & stretch limit gauge Gauge no-3	Checked OK	Checked OK	
9	Check distortion of the coupler head by using aligning wing limit gauge	Checked OK	Checked OK	
10	Checking wear & distortion of coupler head using vertical height aligning wing pocket & guard arm gauge (no-go gauge) Gauge no-1	Checked OK	Checked OK	
11	Checking vertical height alignment & guard arm of coupler in new condition using vertical height alignment wing pocket & guard arm gauge (go gauge) Gauge no-1	Checked OK	Checked OK	
12	Check working of CBC & Anti creep test	Checked OK	Checked OK	
13	Check condition & proper working of CBC operating handle	Checked OK	Checked OK	
14	Check for any crack and damage in Yoke & draft gear	Checked OK	Checked OK	
Supporting device				
15	Visual check for external damage.	Checked OK	Checked OK	
16	Tighten the M16 nut & check height 165.0±1 mm both sides near the bolts.	Checked OK	Checked OK	
17	Check free lateral movement of CBC shank.	Checked OK	Checked OK	
18	Striker wear plate (new-8.00mm & Cond-2.00 mm)	7.15	7.20	
19	CBC height (std-1105 mm & Min-1030 mm)	1092	1060	

Check sheet for Transition screw coupling (MPMI No.25 Rev.00 RDSO Drg.No.SKDL-2894.)

Sr. No	DESCRIPTION	TSC-1	TSC-2	Checked by
1	screw coupling Make & Sr. No.	101C 10/17	RKFL 3123	Rajesh
2	Check for any crackness by DPT/MPT test	DPT OK	DPT OK	JS. Sinha
3	Checking for any damage of thread & operating handle	Checked OK	Checked OK	Rajesh

4	Checking of long & short shackle by Go-No go gauge (long Shackle New-43.0mm cond-39.5mm Short shackle New-28.0mm Cond-25.0mm)	42.85 2770	42.80 2775	prashant
5	Check for any damage of thread & operating handle of screw coupling	Checked OK	Checked OK	Rajesh
6	Check the full operation of screw coupling	Checked OK	Checked OK	
7	Check condition of lock washer	Checked OK	Checked OK	

UST

Sr. No	Axle Box Examination										Checked by		
1	Remove earth cable.										Remove		CE
	Axle box No.-1	Checked OK	Axle box No.--6	Checked OK	Remove						CE		
	Axle box No.--7	Checked OK	Axle box No.--12	Checked OK	Checked OK						Singh		
2	Axle Box cover to remove. Remove lock ring . Clean grease from surface. Check any damaged/abnormality										Remove Clean		HE
3	UST to check by Lab personel. J.S. Sinha.										Checked OK		Rajesh
		1	2	3	4	5	6	7	8	9	10	11	12
	Axle no.	19L 4807	19K 4731	19E 9353	19L 9408	18H 6157	18H 6006						
	Brg. Make	FAG	NBC	FAG	NBC	NBC	FAG						
3 (A)	Axle box old grease to remove fresh grease to fill, old grease sample to lab test for metal content.										Grease Sample Lab		J.S. Sinha
3(B)	'O' ring to change										Fresh Grease Fillup		
3(C)	Axle box cover bolts M-16x45 to torque on 100 NM.										Changed		
	• Clamping plate bolts M-20x50 to torque on 330 NM										All Bolt Torqued		SK
	• Inspection cover bolts M-12x35 to torqued on 85 NM										All Bolt Torqued		CE Singh
	• Erathing plate screw M-10x30 to torqued on 47 NM										All Bolt Torqued		HE Rajesh
4	Axle box greasing to do (as per SMI 246/TC 129 during UST)										All Bolt Torqued		Rajesh
5	Insure all bolts of axle box back cover are tightened.										Greasing done		
6	Temp. 25°C above ambient while in HHP Amb. +56°C										All Bolt Tighten		
7	Greasing for axle box every 2.5 lakh KM or 18 month of service (As per TC-0034 Shell Gadus S5 V 42 p 2.5 to be use.)										Checked OK		
											Shell Gadus S5 V 42 - 0.6 kg each		
8	MSU greasing Clean Grease nipple. Remove grease nipple NDE Side Greasing to do . (Servoplex- SHC120 as per SMI 307 Point no A(vii)) Fit Grease nipple.										Clean Remove NDE Side Greasing done SHC120 Servoplex - 3 kg each		Lalit
9	Wheel distance to measure:-												
	Wheel No.	1	2	3	4	5	6	Checked by					
	Wheel Dist.	1595.95	1595.85	1595.75	1596.40	1596.00	1596.00	Lalit					

Any abnormality noticed during sch. and action taken

NIL

Sign of JE/SSE

Prashant Kumar
Su Rajesh Kumar 4 Su Singh Sinha
Pl-ISA Sign of Tech Mech-ISA