



पश्चिम रेलवे
Western Railway

SABARMATI LOCO SHED
MECHANICAL
IC SCHEDULE FORM WAG-9HC
UNDER FRAME SECTION

Loco No.:- 32461 Arr. Date:- 05-10-2024 Dep. Date:- 08-10-2024
Name of Supervisor:- Sh. Ketan R. Vaghela-SST Shift:- 817 hr Name of Mechanic:- Sh. Sant Kumar

Sr. No	DESCRIPTION (CBC schedule as per G-76)	CBC-1	CBC-2	Checked by
1	CBC No. (Make & Yr)	EASP 131 02/23 RTLA 35 01/19		
2	Check for any crack by MPT test of CBC Assly Items	Checked OK	Checked OK	
	CBC coupler body	Checked OK	Checked OK	
	Knuckle	Checked OK	Checked OK	
	Knuckle Pin (Dia new-41.28 mm, cond-38.00 mm)	40.75	40.80	
	Clevis	Checked OK	Checked OK	
	Clevis Pin (Dia new-38.00 mm, cond-36.00 mm)	37.70	37.65	
Coupler Head				
3	Check tell-tail of the coupler head after coupling	Checked OK	Checked OK	
4	Check cotter pin is installed.	Checked OK	Checked OK	
5	Visual check for external damage, condition of wear plate on shank. (Std-6.00 mm & Cond-1.00 mm)	4.75	4.80	
6	Check gap between coupler head and knuckle with condemning limit gauge. If wear out is not acceptable replace knuckle etc., as advised in the maintenance manual.	Checked OK	Checked OK	
		Checked OK	Checked OK	
7	Check by inspector contour gauge (knuckle profile gauge, go gauge). Gauge no-2	Checked OK	Checked OK	
8	Check wear & stretch of knuckle by using knuckle nose wear & stretch limit gauge Gauge no-3	Checked OK	Checked OK	Vinod
9	Check distortion of the coupler head by using aligning wing limit gauge	Checked OK	Checked OK	
10	Checking wear & distortion of coupler head using vertical height aligning wing pocket & guard arm gauge (no-go gauge) Gauge no-1	Checked OK	Checked OK	
11	Checking vertical height alignment & guard arm of coupler in new condition using vertical height alignment wing pocket & guard arm gauge (go gauge) Gauge no-1	Checked OK	Checked OK	
12	Check working of CBC & Anti creep test	Checked OK	Checked OK	
13	Check condition & proper working of CBC operating handle	Checked OK	Checked OK	
14	Check for any crack and damage in Yoke & draft gear	Checked OK	Checked OK	
Supporting device				
15	Visual check for external damage.	Checked OK	Checked OK	
16	Tighten the M16 nut & check height 165.0±1 mm both sides near the bolts.	Checked OK	Checked OK	
17	Check free lateral movement of CBC shank.	Checked OK	Checked OK	
18	Striker wear plate (new-8.00mm & Cond-2.00 mm)	7.25	7.20	
19	CBC height (std-1105 mm & Min-1030 mm)	1050	1055	

Check sheet for Transition screw coupling (MPMI No.25 Rev.00 RDSO Drg.No.SKDL-2894.)

Sr. No	DESCRIPTION	TSC-1	TSC-2	Checked by
1	screw coupling Make & Sr. No.	18TC 449 10/23	18TC 450 10/23	Vinod
2	Check for any crackness by DPT/MPT test	DPT OK	DPT OK	Nikhil
3	Checking for any damage of thread & operating handle	Checked OK	Checked OK	Vinod

4	Checking of long & short shackle by Go-No go gauge (long Shackle New-43.0mm cond-39.5mm Short shackle New-28.0mm Cond-25.0mm)	42.75 27.65	42.80 27.70	
5	Check for any damage of thread & operating handle of screw coupling	Checked OK	Checked OK	Vinod
6	Check the full operation of screw coupling	Checked OK	Checked OK	
7	Check condition of lock washer	Checked OK	Checked OK	

UST

Sr. No	Axle Box Examination										Checked by			
1	Remove earth cable.										Removed			
	Axle box No.-1			Axle box No.-6				CE- Sudhakar			CE -			
	Axle box No.-7	Checked OK		Axle box No.-12	Checked OK			HE- Harish			Sudhakar			
2	Axle Box cover to remove. Remove lock ring. Clean grease from surface. Check any damaged/abnormality										Removed Cleaned Checked OK		HE Harish	
3	UST to check by Lab personnel. PKB.													
		1	2	3	4	5	6	7	8	9	10	11	12	
	Axle no.	TG 31-25	TG 56-27	TG 24-25	TG 41-22	TG 37-25	TG 56-24							
	Brg. Make	FAG	FAG	FAG-NBC	NBC	FAG	NBC							
3 (A)	Axle box old grease to remove fresh grease to fill, old grease sample to lab test for metal content.										OK by Grease Shell Gadus		Grease Sample by Him	
3(B)	'O' ring to change										Changed			
3(C)	Axle box cover bolts M-16x45 to torque on 100 NM.										All Bolt Torque done			
	• Clamping plate bolts M-20x50 to torque on 330 NM										All Bolt Torque done			
	• Inspection cover bolts M-12x35 to torqued on 85 NM										All Bolt Torque done		Sudhakar Sudhakar	
	• Erathing plate screw M-10x30 to torqued on 47 NM										All Bolt Torque done		Harish	
4	Axle box greasing to do (as per SMI 246/TC 129 during UST)										Greasing done		OK	
5	Insure all bolts of axle box back cover are tightened.										tight done			
6	Temp. 25°C above ambient while in HHP Amb. +56°C										Checked OK			
7	Greasing for axle box every 2.5 lakh KM or 18 month of service (As per TC-0034 Shell Gadus S5 V 42 p 2.5 to be use.)										Greasing done			
8	MSU greasing Clean Grease nipple. Remove grease nipple NDE Side Greasing to do . (Servoplex- SHC120 as per SMI 307 Point no A(vii)) Fit Grease nipple.										Cleaned Removed NDE Side. Greasing done SHC 120- (3) kg		Sudhakar Sudhakar	
9	Wheel distance to measure:-													
	Wheel No.	1	2	3	4	5	6			Checked by				
	Wheel Dist.	1596.90	1596.10	1595.90	1596.45	1597.10	1595.75			Sudhakar				

Any abnormality noticed during sch. and action taken

R₁- Side Buffer Rotted - Changed by - PAG ML.

Wheel No ③ Inner Coil Spring Attended by- Sunit
(Due to Back Side Spring Unlocked)


Sign of JE/SSE

 
Sh. Vinod Bhor 4 Sudhakar f. Harish Dagi
M-I M-I Sign of Tech Mech. I St