



McDOWELL & ASSOCIATES
 Geotechnical, Environmental, & Hydrogeologic Services
 21355 Hatcher Avenue • Ferndale, MI 48220
 Phone: (248) 399-2066 • Fax: (248) 399-2157

JOB NO. 09-017

LOG OF SOIL
BORING NO. 3
PROJECT Soils Investigation - McDonalds Restaurant Renovation

LOCATION 3752 State

Ann Arbor, Michigan

SURFACE ELEV. DATE 2-2-09

Sample & Type	Depth	Legend	SOIL DESCRIPTION	Penetration Blows for 6"	Moisture %	Natural WL P.C.F.	Dry Den WL P.C.F.	Un. Comp. Strength PSF.	Str. %
			0'6" ASPHALT						
	1		1'2" Frozen brown SAND & GRAVEL, aggregate fill						
A	2								
UL	3		Extremely compact frozen to moist brown silty SAND with trace of gravel with stones, possible fill	67	6.4				
	4			38					
B	5		3'9" Compact moist dark brown silty clayey fine SAND with pebbles and clay seams, possible fill	6					
UL	6			12	11.6				
C	7			15					
UL	8		Extremely compact moist brown silty SAND with gravel, stones, some clay and occasional gravelly clay seams	8					
	9			9					
D	10			21					
UL	11								
	12								
	13								
	14								
E	15								
UL	16								
	17								
	18								
	19								
	20								
	21								
	22								
	23								
	24								
	25								

TYPE OF SAMPLE

- D. - DISTURBED
- U.L. - UNDIST. LINER
- S.T. - SHELBY TUBE
- S.S. - SPLIT SPOON
- R.C. - ROCK CORE
- () - PENETROMETER

REMARKS:

Standard Penetration Test - Driving 2" OD Sampler 1' With 140# Hammer Falling 30°: Count Made at 6" Intervals

GROUND WATER OBSERVATIONS

G.W. ENCOUNTERED AT	FT.	INS.
G.W. ENCOUNTERED AT	FT.	INS.
G.W. AFTER COMPLETION	None	
G.W. AFTER	HRS.	
G.W. VOLUMES	FT.	INS.