



**McDOWELL & ASSOCIATES**  
Geotechnical, Environmental, & Hydrogeologic Services  
21355 Hatcher Avenue • Ferndale, MI 48220  
Phone: (248) 399-2066 • Fax: (248) 399-2157

JOB NO. 09-017

**LOG OF SOIL**

BORING NO. 5

BOARING NO. \_\_\_\_\_ Soils Investigation -

**PROJECT** McDonalds Restaurant Renovation

**LOCATION** 3752 State

Ann Arbor, Michigan

**SURFACE ELEV.**                                    **DATE** 2-2-09

DATE 2-2-09

**TYPE OF SAMPLE**

**REMARKS:**

## GROUND WATER OBSERVATIONS

D. - DISTURBED

GW ENCOUNTERED AT ET INS

U.L. + UNDIST. LINER

G.W. ENCOUNTERED AT F1 INS  
G.W. ENCOUNTERED AT F1 INS

S.T. • SHELBY TUBE

G.W. ENCOUNTERED AT PT. INS.  
G.W. AFTER COMPLETION None PT. INS.

S.S. - SPLIT SPOON

R.C. - ROCK CORE  
1-1 RETROGRADE

( ) - PENETROMETER

[View Details](#)

**Standard Penetration Test - Driving 2" OD Sampler 1' With  
140# Hammer Falling 30"; Count Made at 6" Intervals**