This is my potential fix for the Rio Karma's
ethernet problems. Your mileage may vary,
don't try this at home, etc. These values were
determined experimentally. With this fix,
I can reliably connect (with only one light on)
where before I consistently had the two-lights-on
problem.

RJ45
J1

1
2
3
4
5
6
7
8

Ethernet Hub/Switch

R1 56

C1 100pf

RJ45
J2

1
2
3
4
5
6
7
8

Rio Karma Dock

Rio Karma Ethernet Kludge

TITLE

FILE: ethernet-fix.sch

PAGE   1 OF 1

REVISION: A

DRAWN BY: Micah Dowty <micah@navi.cx>