Traditional Pest Control
Unit 3B
Upton Park Farm
Colden Lane
Old Alresford
SO24 9EB

Tel: 07778141505
Email: info@darengeorgeltd.co.uk

Mr Nicholas Scarr
1 Riverside Cottages
The Dean
Alresford
SO24 9BE

Date : 12/03/2025

Report No : 839

Type : Callout

INSPECTION / INFORMATION REPORT

GENERAL OVERVIEW

Call out to the property on 12 March 2025, there has been a major leak of raw sewage from the foul water system into the property. There has been a significant rise in rat activity throughout the three properties in Riverside Cottages since the leak.

19 March 2025 - Follow up visit to check the non toxic monitoring in the foul water drainage system.

24 April 2025 - Follow up visit to undertake a drain survey.

External:

12 March 2025 - The foul water drainage chambers were inspected, in one of the chambers a blanking off cap had been gnawed through by rats allowing them access out of the system.

19 March 2025 - The non toxic monitoring in the foul water system had been eaten by rats.

24 March 2025 - A drain survey was undertaken.

ACTION TAKEN / TREATMENT DETAILS

12 March 2025 - Non toxic monitoring blocks were placed in an inspection chamber in the rear garden to monitor for rat activity.

19 March 2025 - A basic water test was undertaken to establish where all of the foul water leaves the property, it is currently unknown where a pipe running under the property in the chamber by the back door goes to. The chamber nearest to the storm valve was visually inspected, the public sewer has a significant amount of stones, broken pipe etc within it suggesting a defect upstream.

24 April 2025 - The three foul water chambers in the rear garden were cleaned before undertaking the drain survey. The stones, broken pipe etc were removed from the chamber running downstream to the storm valve.

A 4 inch bung was installed in the chamber where the rats have gnawed through the blanking cap.

ENVIRONMENT / RISK ASSESSMENT

Nitrile gloves and coveralls were worn.

PRODUCTS AND AMOUNTS

Detex non toxic monitoring blocks.

4 inch drain bung.

RECOMMENDATIONS / REQUESTS

19 March 2025 - It is recommended that a drain survey is undertaken as soon as possible.

24 April 2025 - You should contact Southern Water immediately, there is a major collapse of the 6 inch pipe in the public sewer approximately 1.2 metres upstream (under your home) of the chamber nearest to the storm valve. This will have been where the sewage has escaped from the system when the valve failed. In addition to this the valve will not currently work correctly as there are stones and other material preventing it to close. This is almost certainly where the rats are leaving the system and entering your home. The room above this has a suspended floor.

SUPPORTING IMAGES



The gnawed blanking cap in one of the chambers, this has been caused by rats.



A bung installed to prevent rats leaving the system.



Stones and rubble under the storm valve.



The 6 inch public sewer, you only find this amount of material in the system when there is a significant defect upstream.



The 6 inch public sewer collapsed under your home.

TECHNICIAN SIGNATURE



Daren George - RSPH Level 2 Award in Pest Management