


NOTES:

- 1. Refer to applicable symbol list.
- 2. Dimensioning and tolerancing per ANSI Y14.5-1973.
- 3. Leads within 127 radius of True Position (TP) at gauge plane with maximum material condition and unit installed.
- 4. c_A and e_B apply in zone L_2 when unit installed.
- 5. a applies to spread leads prior to installation.
- 6. N is the maximum quantity of lead positions.
- 7. N₁ is the allowable quantity of missing leads.
- Outlines on which the scating plane is coincident with the base plane (A₁ = 0) terminal lead standoffs are not required, and B₁ may equal B along any part of the lead above the seating/base plane.
- QUIP Lead Pattern Types are determined by the locations of Lead 1 and Lead N.

Type	Lead	1	Lead	N
A	Inner	₹ow	Inner	Row
В	Outer	₹ow	Outer	Row
	Inner	₹ow	Outer	Row
	Outer	Row	Inner	Row

- 10. Right end top view when N/2 odd.
- 11. Figure A applies.
- 12. Figure B applies.
- 13. Controlling Dimension: INCH

S Y	,			····	VARIATIONS (ALL DIMENSIONS IN MILLIMETERS)									
	,	NA	N	/	\B		1	THE TIMENSTON			- MILLIMETERS/		I N	
M B O L	MIN.	MAX.	Ĭ	MIN.	MAX.	ZOTE	MIN.	Т	MAX.	NOT E	MIN.	MAX.	NOT-E	
A	3.94 .51	5.08 1.27		3.05 .51	4.06 1.65					-			-	
8 8,	. 356 . 89	.508 1.65	8	.356 .89	.508 1.65	8					-			
0 0	.204 18. 9 3	.304 19.93		.204 18.93	. 304 19. 93									
E E ₁	7.62 6.10	8.25 6.60		7.62 6.10	8.25 6.60		_							
•1 •A	2.54 TP 5.08 TP 3,4			2.54 5.08		3.4								
₽ B	10.16 3.18	TP 3.81		10.16 3.18	TP 3.81									
L ₂	.00	. 76 6	6	.00	.76 6	6								
N ₁ Q ₁	1.02	0 1. 9 0	7	1.27	0 2.15	7								
8 E ₂	.39	1.52		.39	1.52			1						
NOTE	1, 2, 9, (Type	B).13		1, 2, 9, (Type	B),13					$\neg +$				
REF.	11.3-34	11.3-34 11.3-35												
ISSUE	A FEB 1976			A FEB 1976										
JEDEC SOLID STATE PRODUCTS					LINE (QUIP)		LY B	JE	DATE 10-1-76		MO-02	.9		
OUTLINES				3.08/	10.10 KOW SPA	TNG				VARI	VARIATIONS AA AND AB			



NOTES:

- 1. Refer to applicable symbol list.
- Dimensioning and tolerancing per ANSI Y14.5-1973.
 Leads within .005radius of True Position (TP) at gauge plane with maximum material condition and unit installed.
- 4. eA and eB apply in zone L2 when unit installed.
 5. a applies to spread leads prior to installation.
- N is the maximum quantity of lead positions.
- 7. N₁ is the allowable quantity of missing leads.
- 8. Outlines on which the seating plane is coincident with the base plane (A1 = 0) terminal lead standoffs are not required, and B1 may equal B along any part of the lead above the seating/base plane.
- 9. QUIP Lead Pattern Types are determined by the locations of Lead I and Lead N.

Type	Lead 1	Lead N
A		Inner Row
В	Outer Row	Outer Row
_ C	Inner Row	
D	Outer Row	Inner Row

- 10. Right end top view when N/2 odd.
- 11. Figure A applies.
- 12. Figure B applies.
 13. Controlling Dimension: INCH

\$					VA	RIAT	IONS	(ALL	DIMENSION	SIN	INCHES)		П							
M B O L		iA.	N AB			N				N O			N							
	MIN.	MAX.	Ť	MIN.	MAX.	P	N	IIN.	MAX.	O T E	MIN.	MAX.	N OT E							
Å	. 155 . 020	. 200 . 050		.120 .020	.160 .065															
8 8 ₁	.014 .035	.020 .065	В	.014 .035	.020 .065	8														
C D	.008 .745	.012 .785		.008 .745	.012 .785															
E E ₁	.300 .240	.325 .260		.300 .240	.325 .260															
*1 *A	.100 TP .200 TP		3,4	. 100 . 200		3,4														
₽B	. 125	TP .150		. 400 . 125) TP .150															
L ₂	.000 1	.030 6	6	.000	.030 16	6_														
N 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7 7	.040	.075	7	.050	.085	7														
\$ E ₂	.015	.060		.015	.060							1								
NOTE	1, 2, 9, (Type B), 13 1, 2, 9, (Type B), 13																			
REF.	11.3-34			11.3-35																
ISSUE	A FEB 1976		_	A FEB 1976																
s	JEDEC SOLID STATE PRODUCTS			TITLE QUAD IN L	.INE (QUIP)	FAMI	ĹY	ISSUE	DATE 10-1-76		MO-0	MO-029								
ł	OUTLINES			.200/.400	ROW SPACING					VARIATIONS AA AND AB										