



11.4 POTENTIOMETERS

MIKROELEKTRONIKA

To test a potentiometer, (pot), or a variable resistor, the process is rather simple – you connect the component to the probes of a meter set to ohms and turn the shaft.

(A “noisy” pot can be repaired using a special spray.)



11.4 Potentiometers by MikroElektronika is licensed under a Creative Commons Attribution 4.0 International License, except where otherwise noted.