Braconier Plumbing & Heating Co., Inc.

Recap with Total Cost

Project Name: Bennett Ranch ELM Phase 2 100

Bid ID: 5918?

Report Time: 11/18/2021 11:51 AM

Profile Name: Standard

Labor Book: Braconier MCA

Scoped By: Base Bid; Drawing: 2M2.1 REV, 2M2.2 REV, 2M2.3 REV, 2M4.1 REV,

2M5.1 REV, 2M5.2 REV, 2M5.3 REV, 2P1.1 REV, 2P1.2 REV, 2P1.3 REV, 2P1.4 REV, 2P2.1 REV, 2P2.2 REV, 2P2.3 REV, 2P2.4 REV, 2P3.1 REV, 2P4.1 REV, 2P4.2 REV, 2P4.3 REV, 2P4.4 REV, 2P4.5 REV, 2P4.6 REV,

2P5.1 REV; System: STORM UG PVC DWV;

AutoBid Version: 2019 v2

Braconier Plumbing & Heating Co., Inc. Recap with Total Cost

There were 61 calculation messages.

Project Name: Bennett Ranch ELM Phase 2 100 Page: 1 of 3

Bid ID: 5918? Report Time: 11/18/21 11:51 AM

Data Calculated: 11/18/2021 11:44:08 AM

Base Bid; Drawing: 2M2.1 REV, 2M2.2 REV, 2M2.3 REV, 2M4.1 REV, 2M5.1 REV, 2M5.2 REV, 2M5.3 REV, 2P1.1 REV, 2P1.2 REV, 2P1.3 REV, 2P1.4 REV, 2P2.1 REV, 2P2.2 REV, 2P2.3 REV, 2P2.4 REV, 2P3.1 REV, 2P4.1 REV, 2P4.2 REV, 2P4.3 REV, 2P4.4 REV, 2P4.5 REV, 2P4.6 REV, 2P5.1 REV, 2P5

| ipe | | | | | | | |
|-------------------------|------------------------|----------------|-----------|--------------------|------------------|-------------------|-------------------|
| PVC - Plain End I | Plastic Sch 40 - Solv | Wld | | | | | |
| Material Multiplier: | : P3900 - PVC Sch 40 | Pipe - CHA | a - 0.55 | | | | |
| <u>Item</u> <u>Size</u> | Quantity | Price | Mat. Cost | Unit Lab Hr | Total Hrs | Labor Cost | Total Cost |
| Pipe | | | | | | | |
| 4 | 25 | 12.18 | 167.48 | 0.09 | 2 | 0 | 167 |
| 6 | 65 | 23.03 | 818.35 | 0.11 | 7 | 0 | 818 |
| 8 | 172 | 35.83 | 3,382.29 | 0.15 | 26 | 0 | 3,382 |
| 10 | 11 | 50.49 | 312.87 | 0.19 | 2 | 0 | 313 |
| PVC - Plain End Pla | astic Sch 40 - SolvWld | Totals: | | | | | |

| PVC - Plain End Pla | astic Sch 40 - SolvWld Totals | S: | | | |
|---------------------|-------------------------------|-------|----|---|-------|
| | 273 | 4,681 | 37 | 0 | 4,681 |
| Pipe Totals: | 273 | 4,681 | 37 | 0 | 4,681 |

Nipples

| PVC - | Plain | End | Sch | 40 - | Thread | |
|-------|-------|-----|-----|------|--------|--|
| | | | | | | |

| Material Multiplier: N3000 - PVC Nipples - 0.54 | | | | | | | | | | | |
|---|---------------------|--------------|-----------|--------------------|-----------|------------|-------------------|--|--|--|--|
| <u>Item</u> <u>Size</u> | Quantity | <u>Price</u> | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | Labor Cost | Total Cost | | | | |
| Nipple | | | | | | | | | | | |
| 6 | 3 | 23.03 | 37.31 | 0.11 | 0 | 0 | 37 | | | | |
| 8 | 6 | 35.83 | 116.09 | 0.15 | 1 | 0 | 116 | | | | |
| 10 | 1 | 50.49 | 27.26 | 0.25 | 0 | 0 | 27 | | | | |
| PVC - Plain End Sch | 40 - Thread Totals: | | | | | | | | | | |

| | 10 | 181 | 1 | 0 | 181 |
|-----------------|----|-----|---|---|-----|
| Nipples Totals: | 10 | 181 | 1 | 0 | 181 |

Fittings

| PVC - GPK Hub x Hub DWV - SolvWld |
|-----------------------------------|
|-----------------------------------|

| Material Multiplier: F | 3B00 - PVC DWV I | Fittings - SI | PE - 0.75 | | | | |
|-------------------------|-------------------|---------------|-----------|--------------------|------------------|-------------------|-------------------|
| <u>Item</u> <u>Size</u> | Quantity | Price | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | Labor Cost | Total Cost |
| Bushing | | | | | | | |
| 10x8 | 1 | 581.63 | 436.22 | 0.50 | 1 | 0 | 436 |
| Wye - Reducing | | | | | | | |
| 10x10x6 | 1 | 834.61 | 625.96 | 0.00 | 0 | 0 | 626 |
| PVC - GPK Hub x Hu | b DWV - SolvWld T | Totals: | | | | | |
| | 2 | | 1,062 | | 1 | 0 | 1,062 |

Braconier Plumbing & Heating Co., Inc. Recap with Total Cost

There were 61 calculation messages.

Project Name: Bennett Ranch ELM Phase 2 100 Page: 2 of 3

Bid ID: 5918? Report Time: 11/18/21 11:51 AM

Data Calculated: 11/18/2021 11:44:08 AM

Base Bid; Drawing: 2M2.1 REV, 2M2.2 REV, 2M2.3 REV, 2M4.1 REV, 2M5.1 REV, 2M5.2 REV, 2M5.3 REV, 2P1.1 REV, 2P1.2 REV, 2P1.3 REV, 2P1.4 REV, 2P2.1 REV, 2P2.2 REV, 2P2.3 REV, 2P2.4 REV, 2P3.1 REV, 2P4.1 REV, 2P4.2 REV, 2P4.3 REV, 2P4.4 REV,

2P4.5 REV, 2P4.6 REV, 2P5.1 REV; System: STORM UG PVC DWV;

Fittings

| PVC - | Huh v | Huh P | lactic | DWV | - SolvWld |
|-------|------------|-------------------|--------|-------|-------------|
| F V L | · (1111) X | . FIIII) F | INSIIC | 17000 | 501V VV ICI |

| Material Multiplier: F3B00 | - CHA - | - PVC DWV Fitti | ngs - CHA - 0.15 |
|----------------------------|---------|-----------------|------------------|
|----------------------------|---------|-----------------|------------------|

36

| <u>Item</u> <u>Size</u> | Quantity | Price | Mat. Cost | Unit Lab Hr | Total Hrs | Labor Cost | Total Cost |
|--------------------------------|-----------------|--------------|-----------|--------------------|------------------|-------------------|-------------------|
| 1/4 Bend Long Sweep | | | | | | | |
| 6 | 2 | 623.97 | 187.19 | 0.67 | 1 | 0 | 187 |
| 1/8 Bend | | | | | | | |
| 6 | 7 | 546.84 | 574.18 | 0.66 | 5 | 0 | 574 |
| 8 | 12 | 715.95 | 1,288.71 | 1.12 | 13 | 0 | 1,289 |
| Combination - Red | | | | | | | |
| 6x6x4 | 1 | 1,542.99 | 231.45 | 0.00 | 0 | 0 | 231 |
| 8x8x4 | 4 | 1,564.65 | 938.79 | 0.00 | 0 | 0 | 939 |
| Coupling | | | | | | | |
| 6 | 1 | 243.34 | 36.50 | 0.63 | 1 | 0 | 37 |
| 8 | 5 | 404.34 | 303.26 | 1.10 | 6 | 0 | 303 |
| Reducing Coupling | | | | | | | |
| 8x6 | 1 | 46.64 | 7.00 | 1.00 | 1 | 0 | 7 |
| Wye | | | | | | | |
| 8 | 1 | 1,520.39 | 228.06 | 1.75 | 2 | 0 | 228 |
| PVC - Hub x Hub Plastic | DWV - SolvWl | d Totals: | | | | | |
| | 34 | | 3,795 | | 28 | 0 | 3,795 |

4,857

4,857

Excav & Backfill - Trenching -

Fittings Totals:

| Material Multiplier: | 1.00 | | | | | | |
|--------------------------|-----------------|--------------|-----------|--------------------|------------------|-------------------|-------------------|
| <u>Item</u> <u>Size</u> | Quantity | Price | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | Labor Cost | Total Cost |
| 2' x 3' Ditch | | | | | | | |
| 4 | 25 | 0.00 | 0.00 | 0.00 | 0 | 0 | 0 |
| 3' x 3' Ditch | | | | | | | |
| 6 | 65 | 0.00 | 0.00 | 0.00 | 0 | 0 | 0 |
| 4' x 3' Ditch | | | | | | | |
| 8 | 172 | 0.00 | 0.00 | 0.00 | 0 | 0 | 0 |
| 4' x 4' Ditch | | | | | | | |
| 10 | 11 | 0.00 | 0.00 | 0.00 | 0 | 0 | 0 |
| - Trenching - Totals: | | | | | | | |
| | 273 | | 0 | | 0 | 0 | 0 |
| Excav & Backfill Totals: | 273 | | 0 | | 0 | 0 | 0 |
| | | | | | | | |

Braconier Plumbing & Heating Co., Inc. Recap with Total Cost

There were 61 calculation messages.

Project Name: Bennett Ranch ELM Phase 2 100 Page: 3 of 3

Bid ID: 5918? Report Time: 11/18/21 11:51 AM

Data Calculated: 11/18/2021 11:44:08 AM

Base Bid; Drawing: 2M2.1 REV, 2M2.2 REV, 2M2.3 REV, 2M4.1 REV, 2M5.1 REV, 2M5.2 REV, 2M5.3 REV, 2P1.1 REV, 2P1.2 REV, 2P1.3 REV, 2P1.4 REV, 2P2.1 REV, 2P2.2 REV, 2P2.3 REV, 2P2.4 REV, 2P3.1 REV, 2P4.1 REV, 2P4.2 REV, 2P4.3 REV, 2P4.4 REV, 2P4.5 REV, 2P4.6 REV, 2P5.1 REV; System: STORM UG PVC DWV;

| Visc. Consumables - Plastic Joints Glue & | Cleaner - | | | | | | |
|---|--------------------|---------------|---------------|--------------------|-----------|-------------------|-----------------|
| Material Multiplier: XNE | | l Price - 1 (| | | | | |
| Item Size | Quantity | Price | Mat. Cost | Unit Lab Hr | Total Hrs | Labor Cost | Total Cost |
| Glue & Cleaner | <u>Q datirorey</u> | 27700 | 1/144 0050 | CHIC LIKE III | 100011115 | 24001 2000 | 1000 |
| Cement - PVC | 31 | 5.89 | 183.39 | 0.00 | 0 | 0 | 18 |
| Cleaner-All Purpose | 31 | 6.33 | 197.08 | 0.00 | 0 | 0 | 19 |
| - Plastic Joints Glue & Cl | eaner - Totals: | | | | | | |
| | 62 | | 380 | | 0 | 0 | 38 |
| Misc. Consumables Totals: | 62 | | 380 | | 0 | 0 | 38 |
| | | | - | | | v | |
| | | | | | | | |
| Pipe Cut | | | | | | | |
| Plastic - Pipe Cut with | Chop Saw - Ch | opSaw | | | | | |
| Material Multiplier: XNE | T - Net Material | l Price - 1.0 | 00 | | | | |
| Item Size | Quantity | Price | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | Labor Cost | Total Cost |
| PIPE CUT | <u> </u> | | | | | | |
| 4 | 5 | 1.00 | 5.00 | 0.00 | 0 | 0 | |
| 6 | 9 | 1.25 | 11.25 | 0.00 | 0 | 0 | 1 |
| 8 | 16 | 1.50 | 24.00 | 0.00 | 0 | 0 | 2 |
| 10 | 3 | 1.50 | 4.50 | 0.00 | 0 | 0 | : |
| Plastic - Pipe Cut with Ch | op Saw - ChopS | aw Totals: | | | | | |
| | 33 | | 45 | | 0 | 0 | 4: |
| Pipe Cut Totals: | 33 | | 45 | | 0 | 0 | 4: |
| | | | | | | | |
| | |] | Material Cost | | Total Hrs | <u>Labor Cost</u> | Total Cos |
| Grand Totals | | | \$10,144 | | 68 | \$0 | \$10,1 4 |

^{*} Items flagged with an asterisk may have their price and labor overwritten in Excel's Rapid Reports