Braconier Plumbing & Heating Co., Inc.

Recap with Total Cost

Project Name: Bennett Ranch ELM School Phase 2

Bid ID: 5918

Report Time: 6/25/2021 12:44 PM

Profile Name: Standard

Labor Book: Braconier MCA

Scoped By: Base Bid; System: STORM UG PVC DWV;

AutoBid Version: 2019 v2

Braconier Plumbing & Heating Co., Inc. Recap with Total Cost

Page: 1 of 3

There were 46 calculation messages.

Project Name: Bennett Ranch ELM School Phase 2

Bid ID: 5918 Report Time: 6/25/21 12:44 PM

Data Calculated: 6/25/2021 12:20:00 PM Base Bid; System: STORM UG PVC DWV;

| D. | |
|----|-----|
| Pī | nρ |
| | DC. |

| Material Multiplier: | : P3900 - PVC Sch 40 | Pipe - CH <i>A</i> | A - 0.55 | | | | |
|-------------------------|------------------------|--------------------|------------------------|-------------|------------------|-------------------|-------------------|
| <u>Item</u> <u>Size</u> | Quantity | Price | Mat. Cost | Unit Lab Hr | Total Hrs | Labor Cost | Total Cost |
| Pipe | | | | | | | |
| 4 | 28 | 5.18 | 79.77 | 0.09 | 3 | 0 | 80 |
| 6 | 84 | 9.78 | 453.95 | 0.11 | 9 | 0 | 454 |
| 8 | 163 | 15.22 | 1,366.53 | 0.15 | 24 | 0 | 1,367 |
| 10 | 10 | 21.44 | 118.71 | 0.19 | 2 | 0 | 119 |
| PVC - Plain End Pla | astic Sch 40 - SolvWld | Totals: | | | | | |
| | 286 | | 2,019 | | 38 | 0 | 2,019 |
| e Totals: | 286 | | 2,019 | | 38 | 0 | 2,019 |

Nipples

| P | VC - | Plain | End | Sch | 40 - | Thread |
|---|------|-------|-----|-----|------|--------|
|---|------|-------|-----|-----|------|--------|

| Material Multiplier: N3000 - PVC Nipples - 0.54 | | | | | | | | | | |
|---|---------------------|--------------|-----------|--------------------|------------------|-------------------|-------------------|--|--|--|
| <u>Item</u> <u>Size</u> | Quantity | Price | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | Labor Cost | Total Cost | | | |
| Nipple | | | | | | | | | | |
| 6 | 3 | 9.78 | 15.84 | 0.11 | 0 | 0 | 16 | | | |
| 8 | 4 | 15.22 | 32.88 | 0.15 | 1 | 0 | 33 | | | |
| 10 | 1 | 21.44 | 11.58 | 0.25 | 0 | 0 | 12 | | | |
| PVC - Plain End Sch | 40 - Thread Totals: | | | | | | | | | |

| | 8 | 60 | 1 | 0 | 60 |
|-----------------|---|----|---|---|----|
| Nipples Totals: | 8 | 60 | 1 | 0 | 60 |

Fittings

PVC - GPK Hub x Hub DWV - SolvWld

| Material Multiplier: F3 | B00 - PVC DWV I | Fittings – SF | PE - 0.75 | | | | |
|-------------------------|-----------------|---------------|-----------|--------------------|------------------|-------------------|-------------------|
| <u>Item</u> <u>Size</u> | Quantity | Price | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | Labor Cost | Total Cost |
| Bushing | | | | | | | |
| 10x8 | 1 | 533.61 | 400.21 | 0.50 | 1 | 0 | 400 |
| Combination - Red | | | | | | | |
| 10x10x4 | 2 | 773.74 | 1,160.61 | 0.00 | 0 | 0 | 1,161 |
| Wye - Reducing | | | | | | | |
| 10x10x6 | 1 | 765.70 | 574.28 | 0.00 | 0 | 0 | 574 |
| PVC - GPK Hub x Hub | DWV - SolvWld T | Totals: | | | | | |
| | 4 | | 2,135 | | 1 | 0 | 2,135 |

Braconier Plumbing & Heating Co., Inc. Recap with Total Cost

Page: 2 of 3

Labor Cost

Total Cost

There were 46 calculation messages.

Project Name: Bennett Ranch ELM School Phase 2

Bid ID: 5918 Report Time: 6/25/21 12:44 PM

Data Calculated: 6/25/2021 12:20:00 PM Base Bid; System: STORM UG PVC DWV;

Fittings

|] | Y | C - | Hub | x Hu | b P | lastic | DV | VV | ′ - SolvWld | |
|---|---|------------|-----|------|-----|--------|----|----|-------------|--|
|---|---|------------|-----|------|-----|--------|----|----|-------------|--|

| Material Multiplier: F3B00 - CHA - PVC DWV Fittings - CHA - 0.15 | | | | | | | | | |
|--|-------------|----------------|---------|-----------|--------------------|------------------|--|--|--|
| <u>Item</u> | <u>Size</u> | <u>Quantit</u> | y Price | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | | | |
| | | | | | | | | | |

| 1/4 Bend Long Sweep | | <u></u> - | | | | | |
|---------------------------|------------|------------|--------|------|----|---|-----|
| 6 | 2 | 471.73 | 141.52 | 0.67 | 1 | 0 | 142 |
| 1/8 Bend | | | | | | | |
| 6 | 7 | 413.41 | 434.08 | 0.66 | 5 | 0 | 434 |
| 8 | 9 | 541.26 | 730.70 | 1.12 | 10 | 0 | 731 |
| Combination | | | | | | | |
| 6 | 1 | 1,296.96 | 194.54 | 0.00 | 0 | 0 | 195 |
| Combination - Red | | | | | | | |
| 8x8x4 | 4 | 1,182.89 | 709.73 | 0.00 | 0 | 0 | 710 |
| Coupling | | | | | | | |
| 6 | 2 | 183.97 | 55.19 | 0.63 | 1 | 0 | 55 |
| 8 | 5 | 305.68 | 229.26 | 1.10 | 6 | 0 | 229 |
| Reducing Coupling | | | | | | | |
| 8x6 | 1 | 46.64 | 7.00 | 1.00 | 1 | 0 | 7 |
| Wye | | | | | | | |
| 8 | 2 | 1,149.42 | 344.83 | 1.75 | 4 | 0 | 345 |
| PVC - Hub x Hub Plastic D | WV - SolvW | ld Totals: | | | | | |
| | | | | | | | |

| | 33 | 2,847 | 27 | 0 | 2,847 |
|------------------|----|-------|----|---|-------|
| Fittings Totals: | 37 | 4,982 | 28 | 0 | 4,982 |

Excav & Backfill

- Trenching -

| Mataria | Multiplier: | 1 00 |
|----------|---------------|----------|
| vialeria | i wiulubiler: | 1.00 |

| <u>Item Size</u> | Quantity | Price | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | Labor Cost | Total Cost |
|--------------------------|-----------------|--------------|-----------|--------------------|------------------|-------------------|-------------------|
| 2' x 3' Ditch | | | | | | | |
| 4 | 28 | 0.00 | 0.00 | 0.00 | 0 | 0 | 0 |
| 3' x 3' Ditch | | | | | | | |
| 6 | 84 | 0.00 | 0.00 | 0.00 | 0 | 0 | 0 |
| 4' x 3' Ditch | | | | | | | |
| 8 | 163 | 0.00 | 0.00 | 0.00 | 0 | 0 | 0 |
| 4' x 4' Ditch | | | | | | | |
| 10 | 10 | 0.00 | 0.00 | 0.00 | 0 | 0 | 0 |
| - Trenching - Totals: | | | | | | | |
| | 286 | | 0 | | 0 | 0 | 0 |
| Excav & Backfill Totals: | 286 | | 0 | | 0 | 0 | 0 |

Braconier Plumbing & Heating Co., Inc. Recap with Total Cost

Page: 3 of 3

There were 46 calculation messages.

Project Name: Bennett Ranch ELM School Phase 2

Bid ID: 5918 Report Time: 6/25/21 12:44 PM

Data Calculated: 6/25/2021 12:20:00 PM Base Bid; System: STORM UG PVC DWV;

| - Plastic Joints Glue & O Material Multiplier: XNET Item Size | | | | | | | |
|---|------------------|--------------|---------------|--------------------|---|-------------------|-------------------|
| <u>Item</u> <u>Size</u> | Γ Not Motorial | | | | | | |
| | i - Net Material | Price - 1.0 | 00 | | | | |
| | Quantity | Price | Mat. Cost | <u>Unit Lab Hr</u> | Total Hrs | Labor Cost | Total Cost |
| Glue & Cleaner | | | | | | | |
| Cement - PVC | 34 | 5.89 | 202.04 | 0.00 | 0 | 0 | 202 |
| Cleaner-All Purpose | 34 | 6.33 | 217.13 | 0.00 | 0 | 0 | 217 |
| - Plastic Joints Glue & Cle | eaner - Totals: | | | | | | |
| | 69 | | 419 | | 0 | 0 | 419 |
| Misc. Consumables Totals: | 69 | | 419 | | 0 | 0 | 419 |
| | | | | | | | 11) |
| | | | | | | | |
| Pipe Cut | | | | | | | |
| Plastic - Pipe Cut with C | Chop Saw - Ch | opSaw | | | | | |
| Material Multiplier: XNET | Γ - Net Material | Price _ 1 (| nn | | | | |
| Item Size | Quantity | Price | Mat. Cost | Unit Lab Hr | Total Hrs | Labor Cost | Total Cost |
| PIPE CUT | Quality | <u> </u> | Matt. Cost | OHI Eus III | Total IIIs | <u>Lubor Cost</u> | Total Cost |
| 4 | 6 | 1.00 | 6.00 | 0.00 | 0 | 0 | ϵ |
| 6 | 10 | 1.25 | 12.50 | 0.00 | 0 | 0 | 13 |
| 8 | 17 | 1.50 | 25.50 | 0.00 | 0 | 0 | 26 |
| 10 | 3 | 1.50 | 4.50 | 0.00 | 0 | 0 | 5 |
| Plastic - Pipe Cut with Cho | p Saw - ChopS | aw Totals: | | | | | |
| | 36 | | 49 | | 0 | 0 | 49 |
| Pipe Cut Totals: | 36 | | 49 | | 0 | 0 | 49 |
| | | | | | | | ., |
| | | , | Material Cost | | Total Hrs | Labor Cost | Total Cost |
| | | 1 | Tatoriai Cost | | 101111111111111111111111111111111111111 | <u>Lator Cost</u> | 10.01 0031 |
| | | | | | | | |

^{*} Items flagged with an asterisk may have their price and labor overwritten in Excel's Rapid Reports