Network Working Group Request for Comments: 112 NIC: 5816 T. O'Sullivan Raytheon Data Systems Company April 1, 1971

User/Server Site Protocol Network HOST Questionnaire (Reference RFC #106, NIC Note 5776)

Attached is a summary of the responses to the referenced questionnaires.

The questions involving terminal support were of interest to members of the User/Service Site Protocol Committee in its considerations of TELNET.

The summary points out some of the key differences between line-at-a-time and character-at-a-time (or both) in handling terminal support, especially with respect to control characters. The information may prove useful as background information to TELNET implementers.

If errors of interpretation of any sites' answer have occurred, please advise me at the following address so that I may update the chart.

Tom O'Sullivan Raytheon Data Systems 1415 Boston-Providence Turnpike Norwood, Massachusetts 02062

[chart: ARPA Network User Terminal Support. Please view the PDF
version of this RFC.]

O'Sullivan [Page 1]