Safety With Electricity

Answers

1 The pool could have been placed out of bounds while work around the pool was in progress.

2 More electrical shocks were experienced in summer because more portable appliances were used outdoors, people were more likely to be barefooted and people tried to fix their own appliances.

3 The hair drier would be carrying a current and this would be transferred to the water in the bath. If a person was in the bath they would conduct the current through their body and receive an electrical shock.

4 Water which is not pure is a good conductor of electricity. If water (dampness) is surrounding electrical appliances or cables it will conduct the current to anyone who touches the appliance or cord.