04	44 Chapthing	and the second of	and the same		terlar and	and the second	at we as because	er en detroduction en deuts et despré de l'article	Alexandra Ada e	G., N.A.R.
06										and a second
06 1	16 13 - Insulating Sheathing									
					Labor-			2022 Bare Costs	1	Total
10010	5 13.10 Insulating Sheathing INSULATING SHEATHING		Crew	Output	Hours	Unit	Material	Labor Equipment	Total	Incl O&P
0020	Expanded polystyrene, 1#/C.F. density, 3/4" thick, R2.89	. G	2 Carp	1400	.011	S.F.	.37	.64	1.01	1.36
0030	1" thick, R3.85	G	z curp	1300	.012	3.F.	.37	.69	1.13	1.50
0040	2" thick, R7.69	G		1200	.012		.72	.75	1.13	1.91
0050	Extruded polystyrene, 15 psi compressive strength, 1" thick, R5	G		1300	.012		.74	.69	1.43	1.84
0060	2" thick, R10	G		1200	.013		.91	.75	1.66	2.12
0070	Polyisocyanurate, 2#/C.F. density, 3/4" thick	G		1400	.011		.81	.64	1.45	1.85
0080	1" thick	G		1300	.012		1	.69	1.69	2.13
0090	1-1/2" thick	G	2 Carp	1250	.013	S.F.	1.19	.72	1.91	2.38
0100	2" thick	G	" "	1200	.013	77	1.52	.75	2.27	2.79
06 1	16 23 - Subflooring									
	23.10 Subfloor									
0010	SUBFLOOR	R061636-20								
0011	Plywood, CDX, 1/2" thick	N00100020	2 Carp	1500	.011	SF Flr.	.76	.60	1.36	1.73
0015	Pneumatic nailed			1860	.009	į.	.76	.48	1.24	1.56
0100	5/8" thick		1	1350	.012		.82	.67	1.49	1.89
0105	Pneumatic nailed			1674	.010		.82	54	1.36	1.70
0200	3/4" thick		İ	1250	.013		.94	.72	1.66	2.11
0205	Pneumatic nailed		1	1550	.010	1 1	.94	.58	1.52	1.91
0300	1-1/8" thick, 2-4-1 including underlayment		1	1050	.015		3.62	.86	4.48	5.25
0440	With boards, 1" x 6", S4S, laid regular			900	.018		2.11	1	3.11	3.81
0450	1" x 8", laid regular			1000	.016		2.16	.90	3.06	3.71
0460	Laid diagonal			850	.019	ì	2.16	1.06	3.22	3.95
0500	1" x 10", laid regular			1100	.015		2.32	.82	3.14	3.77
0600	Laid diagonal		116	900	.018		2.32		3.32	4.04
8990	Subfloor adhesive, 3/8" bead		1 Carp	2300	.003	, L.F.	.10	.20 ;	.30 [.40
	16 26 - Underlayment									
06 16	5 26.10 Wood Product Underlayment									
0010	WOOD PRODUCT UNDERLAYMENT	R061636-20								
0015	Plywood, underlayment grade, 1/4" thick		2 Carp	1500		S.F.	1.85	.60	2.45	2.93
0018	Pneumatic noiled		1	1860	.009		1.85	.48	2.33	2.76
0030	3/8" thick		1	1500	.011		2.06	.60	2.66	3.16
0070	Pneumatic nailed		[]	1860	.009		2.06	.48	2.54	2.99
0100	1/2" thick		1 1	1450	.011		2.75	.62	3.37 3.25	3.95 3.78
0105 0200	Pneumatic nailed 5/8" thick			1400	.011		2.73	.64	3.45	4.05
0205	Pneumatic nailed			1736	.009		2.81	.52	3.33	3.86
0300	3/4" thick			1300	.012		3.08	.69	3.77	4.42
0305	Pneumatic nailed		1	1612	.010		3.08	.56	3.64	4.22
0500	Particle board, 3/8" thick	G		1500	.011		.58	.60	1.18	1.53
0505	Pneumatic nailed	G		1860			.58	.48	1.06	1.36
0600	1/2" thick	G		1450	.011		1	.62	1.62	2.02
0605	Pneumatic nailed	G		1798	.009		1	.50	1.50	1.85
0800	5/8" thick	G		1400	.011		1.03	.64	1.67	2.09
0805	Pneumatic nailed	G		1736	.009		1.03	.52	1.55	1.90
0900	3/4" thick	G		1300	.012		1.06	.69	1.75	2.20
0905	Pneumatic nailed	G	: 🔻	1612	.010	-	1.06	.56	1.62	2
1100	Hardboard, underlayment grade, 4' x 4', .215" thick	G	2 Carp	1500	.011	S.F.	.87	.60	1.47	1.85