			Daily	Labor-			2022 Bare Costs		- 1	Total
02 82	13.44 Demolition In Asbestos Contaminated Area	Crew	Output		Unit	Material	Labor Equip		Total	Incl O&P
0400	Partitions, non load bearing									
0410	Plaster, lath, and studs	A-9	690	.093	S.F.	.73	5.85		6.58	9.7
0450	Gypsum board and studs	"	1390	.046	11	.15	2.91		3.06	4.6
9000	For type B (supplied air) respirator equipment, add				%				10%	10%
	13.45 OSHA Testing									
0010	OSHA TESTING									
0100	Certified technician, minimum				Day		340		340	340
0110	Maximum						670		670	670
0121	Industrial hygienist, minimum						385		385	385
0130	Maximum	1 4-6-	0	1	9	10	755		755	755
0200	Asbestos sampling and PCM analysis, NIOSH 7400, minimum Maximum	1 Asbe	8	1	Ea.	18	63		81 1	116
1000	Cleaned area samples		4 8	2		24 18	126		150	220 116
1100	PCM air sample analysis, NIOSH 7400, minimum		8	1		18	63		81 81	116
1110	Maximum		4	2		24	126		150	220
1200	TEM air sample analysis, NIOSH 7402, minimum		7	7		47	120		80	106
1210	Maximum				-				360	450
	13.46 Decontamination of Asbestos Containment Ar	e a								150
	DECONTAMINATION OF ASBESTOS CONTAINMENT AREA									
0100	Spray exposed substrate with surfactant (bridging)									
0200	Flat surfaces	A-9	6000	.011	S.F.	.44	.67		1.11	1.5
0250	Irregular surfaces		4000	.016	"	.47	1.01		1.48	2.00
0300	Pipes, beams, and columns		2000	.032	L.F.	.63	2.02		2.65	3.78
1000	Spray encapsulate polyethylene sheeting		8000	.008	S.F.	.46	.50		.96	1.28
1100	Roll down polyethylene sheeting		8000	.008	"		.50		.50	.77
1500	Bag polyethylene sheeting		400	.160	Ea.	1.05	10.10		11.15	16.60
2000	Fine clean exposed substrate, with nylon brush		2400	.027	S.F.		1.68		1.68	2.57
2500	Wet wipe substrate		4800	.013			.84		.84	1.29
2600	Vacuum surfaces, fine brush		6400	.010	-		.63		.63	.97
3000	Structural demolition									
3100	Wood stud walls	A-9	2800		S.F.		1.44	1	1.44	2.21
3500	Window manifolds, not incl. window replacement		4200	.015			.96		.96	1.47
3600	Plywood carpet protection	V	2000	.032	¥		2.02		2.02	3.09
4000	Remove custom decontamination facility	A-10A	8	3	Ea.	16.35	190	1	206.35	310
4100	Remove portable decontamination facility	3 Asbe	12	2	"	15	126		141	210
5000	HEPA vacuum, shampoo carpeting	A-9	4800 8000	.013	S.F.	.12	.84 .19		.96 .19	1.42
9000	Final cleaning of protected surfaces	A-10A	0000	.003			.17		.17	.27
	13.47 Asbestos Waste Pkg., Handling, and Disp.							-		
0010	ASBESTOS WASTE PACKAGING, HANDLING, AND DISPOSAL	4.0	400	1/0	Γ.	1.00	10.10		11.20	1/75
0100	Collect and bag bulk material, 3 C.F. bags, by hand	A-9	400	.160	Ea.	1.20 1.01	10.10	.87	11.30 6.47	16.75 9.05
0200	Large production vacuum loader	A-12 A-9	880 960	.073		1.01	4.59 4.21	.07	5.41	7.75
1000	Double bag and decontaminate Containerize bagged material in drums, per 3 C.F. drum	H-7	800	.080		20	5.05		25.05	29.50
2000 3000	Cart bags 50' to dumpster	2 Asbe	400	.040		20	2.52	1	2.52	3.86
5000	Disposal charges, not including haul, minimum	Z Wang	400	.040	C.Y.		L.JL		61 1	67
5020	Maximum				"				355	395
9000	For type B (supplied air) respirator equipment, add				%				10%	10%
	2 13.48 Asbestos Encapsulation With Sealants									
0010	ASBESTOS ENCAPSULATION WITH SEALANTS									
0010		4.0	21000	.003	S.F.	.54	.19		.73	.88
1100	f pilings and walls minimum	13-34								
0100 0110	Ceilings and walls, minimum Maximum	A-9	21000 10600	.003	3.1.	.58	.17		.96	1.22