09 31 Thin-Set Tiling

09 3	1 33 -	Thin-Se	et Stone	Tiling

	Daily Labor-					2022 Bare Costs			
09 31 33.10 Tiling, Thin-Set Stone	Crew	Output	Hours	Unit	Material	Labor	Equipment	Total	Incl 0&P
3290 3" x 12" tile	: D-7	200	.080	S.F.	8.20	3.84		12.04	14.6

09 32 Mortar-Bed	Tiling
------------------	--------

09 32 13 - Mortar-Bed Ceramic Tiling

09 32	13.10 Ceramic Tile					
0010	CERAMIC TILE					
0050	Base, using 1' x 4" high pc. with 1" x 1" tiles	D-7 82 .195 L.F.	4.86	9.35	14.21	193
0600	Cove base, 4-1/4" x 4-1/4" high	91 .176	5.80	8.45	14.25	18.7
0900	6" x 4-1/4" high	. 100 .160	3.24	7.70	10.94	14.7
1200	Sanitary cove base, 6" x 4-1/4" high	93 .172	5.80	8.25	14.05	18.4
1500	6" x 6" high	84 .190	6	9.15	[15.15 [19.9
2400	Bullnose trim, 4-1/4" x 4-1/4"	[82 .195	2.35	9.35	11.70	16.3
2700	2" x 6" bullnose trim	1 👃 84 : .190 ! 👃	1.50	9.15	10.65	15
6210	Wall tile, 4-1/4" x 4-1/4", better grade	1 Tilf 50 .160 S.F.	9	8.50	17.50	22.
6240	2" x 2"	50 .160	7	8.50	15.50	20
6250	6" x 6"	55 .145	8.40	7.75	16.15	20.5
6260	8" x 8"	€ 🕹 60 .133	5.05	7.10	12.15	15.9
6300	Exterior walls, frostproof, 4-1/4" x 4-1/4"	D-7 102 1.157	6.65	7.55	14.20	18.3
6400	1-3/8" x 1-3/8"	93 .172	6.15	8.25	14.40	18.8
6600	Crystalline glazed, 4-1/4" x 4-1/4", plain	1 100 .160	4.28	7.70	[11.98 [15.9
6700	4-1/4" x 4-1/4", scored tile	1 100 1.160	5.95	7.70	13.65	17.3
6900	6" x 6" plain	93172	1.98	8.25	10.23	14.3
7000	For epoxy grout, $1/16''$ joints, $4-1/4''$ tile, add	800 .020	.39	.96	1.35	1.
7200	For tile set in dry mortar, add	1735 .009		.44	.44	
7300	For tile set in Portland cement mortar, add	290 .055	.14	2.65	2.79	4.

09 32 16 - Mortar-Bed Quarry Tiling

09 32 16.10 Quarry Tile

0010	QUARRY TILE							
0100	Base, cove or sanitary, to 5" high, 1/2" thick	D-7	- 110	.145 L.F.	1.50	7	. 8.	.50 11.
0300	Bullnose trim, red, 6" x 6" x 1/2" thick		120	.133	3.53	6.40	9.	.93 · . 13.
0400	4" x 4" x 1/2" thick		110	.145	3.74	7	10.	74 : 14.
0600	4" x 8" x 1/2" thick, using 8" as edge	[]	130	.123	2.95	5.90	8.	.85 11.
0700	Floors, 1,000 S.F. lots, red, 4" x 4" x 1/2" thick		120	.133 S.F.	7.75	6.40	[14.	.15 17.
0900	6" x 6" x 1/2" thick		140	.114	8.45	5.50	13.	.95] 17.
1000	4" x 8" x 1/2" thick	1 +	130	.123	5.30	5.90	11.	.20 1 14.
1300	For waxed coating, add				.68			.68
1500	For non-standard colors, add				.45			.45
1600	For abrasive surface, add				.48			.48
1800	Brown tile, imported, 6" x 6" x 3/4"	D-7	120	.133	7.45	6.40	. 13.	.85 , 17.
1900	8" x 8" x 1"	1 1	1110	1.145	8.50	7	1 15.	.50 1 19.
2100	For thin set mortar application, deduct		700	.023	1	1.10	1.	.10 [1.
2200	For epoxy grout & mortar, 6" x 6" x 1/2", add		350	.046	2.12	2.19	4.	.31 5.
2700	Stair tread, 6" x 6" x 3/4", plain		50	.320	5.15	15.35	20.	.50 28
2800	Abrasive		47	.340	7.75	16.35	24.	.10 32
3000	Wainscot, 6" x 6" x 1/2", thin set, red		105	.152	2.59	7.30	9.	.89 13
3100	Non-standard colors		105	.152 🕌	2.67	7.30	9.	.97 13.
3300	Window sill, 6" wide, 3/4" thick	;	90	.178 L.F.	7.50	8.55	; 16.	.05 21
3400	Corners	1 +	80	.200 ; Ea.	5.45	9.60	15.	.05 20