# 09 35 Chemical-Resistant Tiling

09 3	35 16	- Chemic	cal-Resista	nt Quarr	y Tiling
------	-------	----------	-------------	----------	----------

09 35	5 16.10 Chemical-Resistant Quarry Tiling	Crew		Labor- t Hours		Material	2022 Bare Labor	e Costs Equipment	Total	Total Incl 0&f
0010	CHEMICAL-RESISTANT QUARRY TILING									
0100	4" x 8" x 1/2" thick, 1/8" joint	D-7	130	.123	S.E.	10.75	5.90		16.65	20.:
0200	6" x 6" x 1/2" thick	1 1/	120	.133	1	13.80	6.40		20.20	24.5
0300	8" x 8" x 1/2" thick	:	110	145		9.90	. 7		16.90	21
0400	4" x 8" x 1/2" thick, 1/4" joint		130	.123		12.35	5.90		18.25	22.
0500	6" x 6" x 1/2" thick	i 17	120	.133		15.25	6.40		21.65	26
0600	8" x 8" x 1/2" thick		110	.145		10.70	7		17.70	22
0700	4" x 8" x 1/2" thick, 3/8" joint		130	.123		13.75	5.90		19.65	24
0800	6" x 6" x 1/2" thick		120	.133		16.45	6.40		22.85	27.
0900	8" x 8" x 1/2" thick	1 1	110	.145	+	12.25	7 :		19.25	23.

## 09 51 Acoustical Ceilings

09 51 13 -	Acoustical	Panel	Ceilings
------------	------------	-------	----------

09 51	13.10	Ceiling.	Acoustical	Panel

0010	CEILING, ACOUSTICAL PANEL								
0100	Fiberglass boards, film faced, 2' x 2' or 2' x 4', 5/8" thick	1 Carp	625	.013	S.F.	4.59	.72	5.31	
0120	3/4" thick		600	.013	1 :	4.96	.75	5.71	
0130	3" thick, thermal, R11	. 🗼	450	.018	₩ '	4.19	1 :	 5.19 : .	

### 09 51 14 - Acoustical Fabric-Faced Panel Ceilings

09 51 14.10	Ceiling,	Acoustical	Fabric-Faced	Panel
-------------	----------	------------	--------------	-------

0010 CEILING, ACOUSTICAL FABRIC-FACED PANEL	
O100 Glass cloth faced fiberglass, 3/4" thick 1 Carp 500 .016 S.F.	3.38 .90 4.28 :
0120 3" thick 485 .016	7.25 .93 8.18
0130 1-1/2" thick, nubby face ; 475 .017 🐳	2.85 .95 3.80

### 09 51 23 - Acoustical Tile Ceilings

09 51	23.10 Suspended Acoustic Ceiling Illes										
0010	SUSPENDED ACOUSTIC CEILING TILES, not including										
0100	suspension system		1 4								
1110	Mineral fiber tile, lay-in, 2' x 2' or 2' x 4', 5/8" thick, fine texture		1 Carp	625	.013	S.F.	2.25	.72		2.97	3
1115	Rough textured .			625	.013		1.17	.72		1.89	2
1125	3/4" thick, fine textured			600	.013		2.16	.75		2.91	3.
1130	Rough textured			600	.013		2.07	.75		2.82	3
1135	Fissured		111	600	.013		2.28	.75	1	3.03	3
1150	Tegular, 5/8" thick, fine textured			470	.017		2.55	.96		3.51	4
1155	Rough textured			470	.017		1.92	.96		2.88	3.
1165	3/4" thick, fine textured		.;	450	.018	*Harden American	4.26	1		5.26	6.
1170	Rough textured		:	450	.018	- Programma	1.42	1 1 2		2.42	3
1175	Fissured		: 1	450	.018	Appropriate sections	1.77	1		2.77	3
1185	For plastic film face, add						.76			.76	
1190	For fire rating, add		1 1				.55			.55	
3720	Mineral fiber, 24" x 24" or 48", reveal edge, painted, 5/8" thick		1 Carp	600	.013		1.55	.75		2.30	2
3740	3/4" thick			575	.014		1.77	.78		2.55	3
5020	66-78% recycled content, 3/4" thick	G		600	.013		6.90	.75		7.65	8
5040	Mylar, 42% recycled content, 3/4" thick	G		600	.013		4.85	.75		5.60	6
6000	Remove & install new ceiling tiles, min fiber, 2' x 2' or 2' x 4', 5/8"thk.		: 😾	335	.024	+	2.25	1.34		3.59	4