Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0



ARM Verification IP AMBA 4 ACE and ACE-Lite Protocol Checkers (BP065) Errata Notice

This document contains all errata known at the date of issue in releases up to and including revision r0p1

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Proprietary notice

Words and logos marked with ® or ™ are registered trademarks or trademarks of ARM[®] in the EU and other countries, except as otherwise stated below in this proprietary notice. Other brands and names mentioned herein may be the trademarks of their respective owners.

Neither the whole nor any part of the information contained in, or the product described in, this document may be adapted or reproduced in any material form except with the prior written permission of the copyright holder.

The product described in this document is subject to continuous developments and improvements. All particulars of the product and its use contained in this document are given by ARM in good faith. However, all warranties implied or expressed, including but not limited to implied warranties of merchantability, or fitness for purpose, are excluded.

This document is intended only to assist the reader in the use of the product. ARM shall not be liable for any loss or damage arising from the use of any information in this document, or any error or omission in such information, or any incorrect use of the product.

Where the term ARM is used it means "ARM or any of its subsidiaries as appropriate".

Document confidentiality status

This document is Non Confidential.

Web address

http://www.arm.com/

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Feedback on the product

If you have any comments or suggestions about this product, contact your supplier giving:

- The product name
- A concise explanation of your comments.

Feedback on this document

If you have any comments on about this document, please send email to mailto:errata@arm.com giving:

- The document title
- The documents number
- The page number(s) to which your comments refer
- A concise explanation of your comments

General suggestion for additions and improvements are also welcome.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Contents

INTRODUCTION	5
There are no errata in this document.	6
ERRATA SUMMARY TABLE	7
There are no errata in this document.	7
ERRATA - CATEGORY 1	8
There are no errata in this category.	8
ERRATA - CATEGORY 2	9
There are no errata in this category.	9
ERRATA - CATEGORY 3	10
There are no errata in this category.	10
ERRATA - IMPLEMENTATION	11
There are no errata in this category.	11
ERRATA - SYSTEM	12
There are no errata in this category.	12
ERRATA - DOCUMENTATION	13
There are no errata in this category.	13

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Introduction

Scope

This document describes errata categorised by level of severity. Each description includes:

- the current status of the defect
- where the implementation deviates from the specification and the conditions under which erroneous behavior occurs
- the implications of the erratum with respect to typical applications
- the application and limitations of a 'work-around' where possible

Categorisation of Errata

Errata recorded in this document are split into three levels of severity:

Category 1	Behavior that is impossible to work around and that severely restricts the use of the product in all, or the majority of applications, rendering the device unusable.
Category 2	Behavior that contravenes the specified behavior and that might limit or severely impair the intended use of specified features, but does not render the product unusable in all or the majority of applications.
Category 3	Behavior that was not the originally intended behavior but should not cause any problems in applications.
Implementation	Errata that are of particular interest to those implementing the product and that have no software implications
System	Errata or possible issues that have system implications and therefore should be considered by system designers
Documentation	Errors in the Documentation that may have implications for programmers, system designers or programmers resulting in incorrect behaviour or the ARM Core.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Change Control

Errata are listed in this section if they are new to the document, or marked as "updated" if there has been any change to the text of the erratum Description, Conditions, Implications or Workaround. Fixed errata are not shown as updated, unless the erratum text has changed. The summary table identifies errata that have been fixed in each product revision.

There are no errata in this document.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Errata Summary Table

The errata associated with this product affect product versions as below.

A cell shown thus **X** indicates that the defect affects the revision shown at the top of that column.

There are no errata in this document.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Errata - Category 1

There are no errata in this category.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Errata - Category 2

There are no errata in this category.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Errata - Category 3

There are no errata in this category.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Errata - Implementation

There are no errata in this category.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Errata - System

There are no errata in this category.

Date of Issue: 02 Apr 2012 ARM Errata Notice Document Revision 2.0

Errata – Documentation

There are no errata in this category.