CAPITAL IMPROVEMENT PLAN

Elmhurst Senior Living | Naperville, IL

Property	Elmhurst Senior Living
Plan Date	September 20, 2025
Prepared For	Keel & Compass Properties
Total Plan Budget	$431,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Roof replacement - Bldg B	Building	02/19/25	Q1 2026	$509,000	$500,538	Complete
Landscape / irrigation	Building	07/07/23	Q2 2025	$752,000	$456,369	In progress
Pool resurfacing	Interior	07/15/26	Q1 2026	$535,000	$307,150	Approved
Sewer line repair	Energy	05/26/25	Q4 2027	$202,000	$180,748	Complete
LED lighting retrofit	Site	06/25/23	Q1 2027	$727,000	$23,227	Complete
Lobby renovation	Site	07/25/24	Q4 2027	$145,000	$131,357	Deferred
Sewer line repair	Energy	05/27/23	Q2 2025	$550,000	$246,757	Deferred
Security camera upgrade	Life Safety	01/29/24	Q3 2027	$36,000	$7,037	Approved
Pool resurfacing	Interior	06/22/25	Q1 2027	$130,000	$70,892	Complete
HVAC replacement	Site	03/25/25	Q3 2027	$800,000	$423,732	Complete
ADA compliance	Site	03/10/23	Q4 2027	$290,000	$16,851	Bidding
Sewer line repair	Energy	10/30/24	Q4 2026	$191,000	$185,253	Complete
Signage / monument	Energy	12/23/26	Q4 2026	$202,000	$208,228	In progress
HVAC replacement	Energy	05/28/26	Q1 2026	$757,000	$443,235	Deferred
Landscape / irrigation	Site	12/16/24	Q2 2026	$145,000	$48,657	Complete
Door hardware	Site	08/26/26	Q2 2026	$245,000	$38,277	In progress
Sewer line repair	Site	04/10/24	Q4 2027	$41,000	$37,505	Bidding
Parking lot resurfacing	Life Safety	01/02/24	Q1 2025	$70,000	$58,249	Deferred
Sewer line repair	Interior	09/30/23	Q3 2026	$782,000	$501,941	Approved
Fire alarm panel upgrade	Interior	11/12/24	Q4 2026	$337,000	$111,626	In progress
Parking lot resurfacing	Life Safety	05/02/23	Q2 2025	$682,000	$448,883	Bidding
Sewer line repair	Energy	12/13/24	Q1 2026	$769,000	$386,241	Complete
Elevator modernization	Life Safety	02/06/24	Q3 2027	$898,000	$139,195	Deferred
Elevator modernization	Energy	01/26/25	Q3 2026	$301,000	$49,680	Bidding
Unit interior upgrades	Site	10/31/23	Q2 2025	$348,000	$199,229	Deferred

Report generated 09/20/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
HVAC replacement	Building	06/21/26	Q3 2025	$249,000	$80,505	In progress
Door hardware	Interior	04/27/25	Q4 2026	$73,000	$27,870	Bidding
Security camera upgrade	Energy	10/02/26	Q3 2025	$312,000	$136,835	In progress
ADA compliance	Building	01/15/23	Q3 2025	$329,000	$148,772	Complete
LED lighting retrofit	Site	12/25/25	Q3 2026	$211,000	$67,264	Deferred
Water heater replacement	Energy	12/29/25	Q1 2027	$71,000	$32,749	In progress
Parking lot resurfacing	Site	02/15/25	Q3 2025	$557,000	$74,594	Complete
Roof replacement - Bldg C	Interior	11/20/23	Q1 2026	$360,000	$258,672	Bidding
Water heater replacement	Building	08/19/25	Q4 2026	$48,000	$13,626	Deferred
Roof replacement - Bldg B	Building	10/06/25	Q3 2027	$677,000	$327,811	Bidding
Unit interior upgrades	Interior	01/10/24	Q2 2027	$553,000	$141,513	In progress
Roof replacement - Bldg C	Energy	04/10/26	Q3 2025	$10,000	$992	Complete
Landscape / irrigation	Building	07/04/26	Q1 2025	$256,000	$253,194	Bidding
Parking lot resurfacing	Building	04/03/25	Q3 2026	$39,000	$14,556	Complete
Signage / monument	Site	02/04/25	Q1 2027	$275,000	$112,771	In progress
Sewer line repair	Building	08/24/23	Q4 2027	$493,000	$327,911	In progress
Fire alarm panel upgrade	Life Safety	12/15/24	Q2 2027	$374,000	$299,474	Complete
HVAC replacement	Building	10/08/23	Q2 2026	$746,000	$354,658	Approved
Water heater replacement	Energy	02/08/23	Q4 2027	$81,000	$38,638	Complete
Storefront glazing	Energy	01/10/25	Q4 2027	$233,000	$222,854	Approved
Exterior paint	Energy	12/26/26	Q2 2027	$147,000	$36,778	Approved
HVAC replacement	Interior	09/03/25	Q4 2026	$291,000	$209,615	Deferred
Signage / monument	Life Safety	03/02/25	Q4 2026	$884,000	$541,763	Approved
Elevator modernization	Site	12/06/25	Q1 2027	$534,000	$254,620	Complete
Signage / monument	Site	02/07/24	Q1 2027	$257,000	$266,597	Bidding
Roof replacement - Bldg D	Building	03/19/23	Q1 2027	$722,000	$424,217	Approved
Fence replacement	Energy	03/21/26	Q3 2026	$397,000	$240,520	Deferred
Signage / monument	Interior	02/22/26	Q1 2027	$801,000	$440,977	In progress
Pool resurfacing	Site	02/14/26	Q2 2026	$563,000	$484,600	Approved
Security camera upgrade	Building	04/09/23	Q1 2026	$724,000	$7,910	Approved
Storefront glazing	Life Safety	04/11/25	Q4 2027	$222,000	$9,415	Bidding
Roof replacement - Bldg C	Interior	12/05/25	Q2 2027	$193,000	$151,822	Approved
Signage / monument	Building	01/23/26	Q3 2026	$205,000	$5,921	In progress
Fence replacement	Life Safety	09/15/24	Q1 2027	$735,000	$417,703	Bidding
Unit interior upgrades	Building	06/07/26	Q2 2026	$896,000	$599,976	Deferred
Fire alarm panel upgrade	Building	07/05/23	Q3 2025	$870,000	$575,889	Deferred
HVAC replacement	Life Safety	08/01/26	Q2 2025	$143,000	$130,866	Deferred
Storefront glazing	Energy	01/07/26	Q1 2026	$9,000	$3,803	Complete
Storefront glazing	Life Safety	05/26/24	Q3 2025	$194,000	$178,104	Bidding
HVAC replacement	Interior	02/22/26	Q2 2026	$399,000	$204,253	Deferred

Report generated 09/20/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $429,000. Elevators were last modernized 10 years ago and are operating without deficiency. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 26 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $206,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 46 months. Elevators were last modernized 5 years ago and are operating without deficiency.

Investment Overview

Dining, housekeeping, transportation and activities programming are included in the base fee. Projected levered IRR is 5.7% with an equity multiple of 1.42x over the hold period. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

The business plan contemplates a hold period of 11 years with disposition upon achievement of target returns. Dining, housekeeping, transportation and activities programming are included in the base fee. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Occupancy stands at 88.9% with an average resident length of stay of 9 years.

Deferred Maintenance

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $399,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 34 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 29 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Business Plan Progress

Distributions to investors for the quarter were paid at an annualized rate of 5.4% on contributed capital. The business plan contemplates a hold period of 4 years with disposition upon achievement of target returns. Dining, housekeeping, transportation and activities programming are included in the base fee. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Projected levered IRR is 5.7% with an equity multiple of 1.37x over the hold period.

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The community provides assisted living and memory care services under a state-issued license with 44 full-time caregivers per shift. Distributions to investors for the quarter were paid at an annualized rate of 4.4% on contributed capital. The business plan contemplates a hold period of 9 years with disposition upon achievement of target returns. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market.

Recommendations

Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 4 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 17 months.

Elevators were last modernized 12 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Business Plan Progress

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Door hardware	Interior	04/22/25	Q3 2027	$368,000	$332,199	Approved
Door hardware	Building	05/22/24	Q1 2026	$161,000	$13,108	Deferred
LED lighting retrofit	Building	06/04/26	Q4 2026	$757,000	$792,467	Bidding
ADA compliance	Site	10/20/26	Q1 2025	$202,000	$49,345	Complete
Fence replacement	Site	02/16/24	Q3 2026	$697,000	$28,812	Deferred
Unit interior upgrades	Energy	09/15/25	Q4 2025	$712,000	$81,614	Approved
Fire alarm panel upgrade	Energy	01/03/25	Q1 2025	$643,000	$527,063	Bidding
Signage / monument	Site	03/15/25	Q1 2026	$347,000	$165,891	Approved
Exterior paint	Energy	03/02/25	Q1 2025	$262,000	$155,788	In progress
Exterior paint	Life Safety	03/15/26	Q3 2025	$291,000	$65,764	Bidding
Unit interior upgrades	Interior	12/13/23	Q2 2025	$11,000	$2,696	Deferred
Fence replacement	Building	07/22/25	Q4 2027	$724,000	$484,189	Bidding
HVAC replacement	Energy	04/03/24	Q1 2025	$180,000	$43,834	Deferred
Fire alarm panel upgrade	Site	12/11/24	Q3 2026	$20,000	$5,492	Complete
Exterior paint	Life Safety	11/01/23	Q3 2027	$475,000	$414,249	Approved
Lobby renovation	Energy	01/09/24	Q4 2027	$121,000	$34,815	Deferred
Amenity renovation	Site	05/23/24	Q3 2026	$881,000	$109,347	Complete
Storefront glazing	Energy	07/06/26	Q3 2026	$434,000	$3,276	Deferred
Security camera upgrade	Interior	11/25/26	Q1 2026	$804,000	$161,649	Deferred
Storefront glazing	Interior	11/12/25	Q3 2026	$745,000	$416,137	Deferred
Signage / monument	Life Safety	06/21/25	Q3 2025	$387,000	$220,211	Complete
ADA compliance	Life Safety	11/29/26	Q3 2026	$763,000	$380,590	Deferred
ADA compliance	Site	09/16/26	Q2 2025	$264,000	$55,994	Approved
Amenity renovation	Site	04/04/23	Q2 2027	$595,000	$447,741	Approved
Fire alarm panel upgrade	Life Safety	05/17/24	Q4 2025	$576,000	$33,733	Approved
Water heater replacement	Site	01/19/25	Q3 2027	$225,000	$56,756	Complete
Security camera upgrade	Energy	03/30/26	Q3 2026	$665,000	$293,183	Approved
Elevator modernization	Energy	10/20/24	Q2 2026	$783,000	$234,222	Deferred
Fire alarm panel upgrade	Building	08/30/26	Q1 2025	$209,000	$92,197	Approved
Signage / monument	Energy	06/02/23	Q2 2025	$292,000	$292,196	Complete
Roof replacement - Bldg A	Life Safety	03/03/25	Q1 2025	$582,000	$182,021	In progress
Landscape / irrigation	Energy	04/06/24	Q3 2027	$653,000	$33,217	Bidding
Door hardware	Building	06/12/25	Q3 2026	$392,000	$295,811	Bidding
Sewer line repair	Life Safety	04/12/26	Q2 2026	$108,000	$96,478	In progress
Unit interior upgrades	Energy	03/05/23	Q1 2025	$24,000	$6,920	Deferred
Storefront glazing	Interior	04/23/26	Q1 2027	$654,000	$365,781	Complete
Security camera upgrade	Energy	12/30/24	Q1 2026	$845,000	$200,226	In progress
Sewer line repair	Energy	09/18/24	Q2 2025	$835,000	$630,386	Deferred
Elevator modernization	Energy	05/19/26	Q2 2025	$842,000	$105,611	Approved
Signage / monument	Interior	09/26/23	Q1 2025	$296,000	$2,926	Deferred
Lobby renovation	Site	12/11/23	Q2 2027	$199,000	$166,741	Deferred

Report generated 09/20/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Domestic water piping is copper and PVC with no evidence of widespread leakage. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $145,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Elevators were last modernized 7 years ago and are operating without deficiency.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 8 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $168,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 13 months.

Risk Considerations

Projected levered IRR is 11.6% with an equity multiple of 1.45x over the hold period. Dining, housekeeping, transportation and activities programming are included in the base fee. The community provides assisted living and memory care services under a state-issued license with 40 full-time caregivers per shift. The business plan contemplates a hold period of 12 years with disposition upon achievement of target returns.

The community provides assisted living and memory care services under a state-issued license with 28 full-time caregivers per shift. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care. Dining, housekeeping, transportation and activities programming are included in the base fee. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Occupancy stands at 91.2% with an average resident length of stay of 11 years. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Observed Conditions

Elevators were last modernized 5 years ago and are operating without deficiency. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 22 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $378,000.

Domestic water piping is copper and PVC with no evidence of widespread leakage. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $132,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Risk Considerations

The business plan contemplates a hold period of 6 years with disposition upon achievement of target returns. Projected levered IRR is 11.5% with an equity multiple of 1.17x over the hold period. Dining, housekeeping, transportation and activities programming are included in the base fee. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care.

The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. Occupancy stands at 94.8% with an average resident length of stay of 10 years. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Dining, housekeeping, transportation and activities programming are included in the base fee. Projected levered IRR is 6.9% with an equity multiple of 1.43x over the hold period.

Recommendations

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 6 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $169,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 7 months.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $310,000. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Roof replacement - Bldg D	Life Safety	01/23/26	Q2 2027	$711,000	$467,605	Complete
LED lighting retrofit	Life Safety	12/18/26	Q2 2027	$486,000	$505,817	Complete
Sewer line repair	Building	11/20/23	Q4 2026	$743,000	$30,907	Bidding
Landscape / irrigation	Interior	09/29/25	Q2 2026	$769,000	$156,750	Complete
ADA compliance	Interior	04/07/26	Q4 2025	$31,000	$10,934	Deferred
Signage / monument	Building	04/07/24	Q4 2026	$225,000	$7,004	Complete
Exterior paint	Site	04/15/23	Q1 2025	$440,000	$268,328	Bidding
Landscape / irrigation	Energy	09/19/26	Q2 2027	$631,000	$260,163	Approved
Lobby renovation	Interior	06/03/24	Q1 2025	$671,000	$16,598	Bidding
Fire alarm panel upgrade	Energy	07/25/24	Q4 2026	$224,000	$67,371	Complete
Parking lot resurfacing	Energy	04/19/26	Q3 2027	$475,000	$75,243	Approved
Parking lot resurfacing	Interior	10/08/23	Q2 2026	$62,000	$21,406	Complete
Roof replacement - Bldg A	Energy	08/10/26	Q4 2025	$363,000	$23,871	Approved
LED lighting retrofit	Building	12/25/26	Q1 2026	$565,000	$277,091	Bidding
Amenity renovation	Life Safety	01/19/25	Q3 2025	$597,000	$624,609	Approved
Door hardware	Building	12/02/24	Q1 2027	$858,000	$884,987	Bidding
Fire alarm panel upgrade	Energy	12/25/24	Q2 2025	$176,000	$168,620	Approved
ADA compliance	Site	06/08/26	Q4 2025	$532,000	$329,162	In progress
Storefront glazing	Life Safety	08/28/23	Q1 2026	$663,000	$106,841	Deferred
Fence replacement	Building	02/28/23	Q4 2025	$702,000	$80,768	Bidding
ADA compliance	Energy	05/29/25	Q3 2026	$229,000	$53,608	In progress
Fire alarm panel upgrade	Life Safety	08/09/25	Q1 2025	$31,000	$31,467	Bidding
HVAC replacement	Life Safety	06/24/23	Q2 2025	$840,000	$247,867	Deferred
Lobby renovation	Building	03/28/25	Q3 2025	$436,000	$331,461	In progress
Pool resurfacing	Energy	03/01/23	Q4 2027	$435,000	$189,571	Complete
Amenity renovation	Life Safety	09/25/26	Q2 2025	$790,000	$564,659	Deferred
Door hardware	Energy	01/11/24	Q4 2027	$271,000	$270,751	Approved
Water heater replacement	Energy	02/23/25	Q3 2027	$366,000	$255,442	Bidding
Roof replacement - Bldg D	Site	10/04/24	Q2 2027	$412,000	$10,583	In progress
Amenity renovation	Life Safety	06/25/24	Q1 2027	$425,000	$199,544	Bidding
LED lighting retrofit	Energy	11/08/24	Q1 2026	$244,000	$204,737	Complete
Door hardware	Interior	06/28/25	Q2 2025	$243,000	$202,863	Deferred
Unit interior upgrades	Site	03/21/25	Q2 2025	$636,000	$421,269	Bidding
Landscape / irrigation	Site	08/13/24	Q3 2026	$809,000	$282,177	Deferred
Water heater replacement	Energy	01/14/24	Q4 2027	$611,000	$257,072	Bidding
Water heater replacement	Building	10/02/24	Q2 2026	$201,000	$206,121	In progress
Pool resurfacing	Interior	09/03/25	Q2 2026	$269,000	$139,675	Deferred
Unit interior upgrades	Life Safety	11/08/23	Q3 2025	$797,000	$658,075	Bidding
Pool resurfacing	Site	11/09/24	Q4 2025	$226,000	$193,325	Complete
Fire alarm panel upgrade	Life Safety	06/16/24	Q4 2027	$840,000	$21,285	Approved
Water heater replacement	Site	08/12/24	Q3 2026	$255,000	$223,664	In progress
Door hardware	Energy	01/11/23	Q4 2027	$489,000	$21,457	Complete
Landscape / irrigation	Building	02/01/23	Q4 2026	$73,000	$75,477	Complete

Report generated 09/20/2025. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Summary and Notes

Valuation Discussion

Debt service coverage ratio was 6.39x on a trailing basis against a covenant minimum of 1.20x. Net operating income is projected to grow at a compound annual rate of 7.5% over the hold period. A reserve for replacements of $250 per unit has been underwritten in the cash flow below net operating income. The community provides assisted living and memory care services under a state-issued license with 44 full-time caregivers per shift.

Occupancy stands at 90.4% with an average resident length of stay of 11 years. Net operating income is projected to grow at a compound annual rate of 7.7% over the hold period. A reserve for replacements of $250 per unit has been underwritten in the cash flow below net operating income. The community provides assisted living and memory care services under a state-issued license with 41 full-time caregivers per shift. Effective gross income for the trailing period was $383,000, representing a 4.0% increase over the prior year. Dining, housekeeping, transportation and activities programming are included in the base fee.

Leasing and Marketing

On-site staffing consists of a property manager, assistant manager, maintenance supervisor and 36 additional team members. Preventive maintenance schedules for HVAC, elevators and life-safety systems were completed on time during the period. The manager completes a monthly walk of the property and submits a variance report to the owner by the 25th business day. The community provides assisted living and memory care services under a state-issued license with 33 full-time caregivers per shift. Dining, housekeeping, transportation and activities programming are included in the base fee.

Collections for the period were 89.7% of billed charges, with bad debt of 6.0% of gross potential income. Service requests are tracked through a work-order system with an average completion time of 6 hours. Dining, housekeeping, transportation and activities programming are included in the base fee. Average monthly revenue per occupied unit is $5,108, inclusive of base rent and levels of care.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only