CAPITAL IMPROVEMENT PLAN

Cobalt Data Campus | Nashville, TN

Property	Cobalt Data Campus
Plan Date	January 22, 2026
Prepared For	Sunbelt Ridge Acquisitions
Total Plan Budget	$103,000

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
ADA compliance	Energy	08/12/25	Q3 2027	$813,000	$411,311	In progress
Landscape / irrigation	Building	07/26/25	Q4 2025	$486,000	$219,736	Approved
Fence replacement	Energy	01/05/26	Q2 2026	$869,000	$664,736	Bidding
ADA compliance	Building	02/01/24	Q3 2027	$504,000	$247,415	Bidding
Signage / monument	Site	06/14/23	Q1 2025	$898,000	$759,695	Complete
Fire alarm panel upgrade	Site	03/13/23	Q1 2027	$24,000	$2,327	Deferred
Unit interior upgrades	Building	12/14/25	Q4 2026	$65,000	$30,579	Approved
Exterior paint	Energy	04/13/24	Q3 2025	$616,000	$277,932	Complete
HVAC replacement	Interior	10/10/23	Q2 2026	$139,000	$139,927	Complete
Parking lot resurfacing	Interior	03/16/23	Q1 2025	$435,000	$141,986	Bidding
ADA compliance	Energy	08/20/25	Q2 2027	$643,000	$276,105	Complete
Storefront glazing	Life Safety	10/03/26	Q2 2026	$246,000	$43,576	Approved
Storefront glazing	Energy	02/23/24	Q1 2025	$190,000	$105,684	Complete
Storefront glazing	Interior	01/05/24	Q1 2026	$206,000	$181,880	In progress
Exterior paint	Building	09/17/23	Q2 2026	$800,000	$562,719	Bidding
Pool resurfacing	Interior	07/30/26	Q2 2027	$531,000	$460,001	Approved
Elevator modernization	Building	01/22/26	Q4 2025	$251,000	$100,433	In progress
Amenity renovation	Life Safety	05/22/25	Q2 2026	$123,000	$98,566	In progress
Security camera upgrade	Building	02/04/26	Q4 2026	$760,000	$693,998	Approved
Security camera upgrade	Site	08/09/26	Q1 2026	$238,000	$135,265	Complete
Signage / monument	Energy	02/23/23	Q2 2025	$522,000	$517,757	Bidding
Lobby renovation	Interior	11/29/26	Q1 2025	$767,000	$226,675	Approved

Report generated 01/22/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Roof replacement - Bldg A	Interior	07/18/23	Q1 2025	$402,000	$152,860	Deferred
LED lighting retrofit	Interior	03/26/26	Q4 2026	$741,000	$414,030	Bidding
LED lighting retrofit	Site	02/11/25	Q4 2026	$719,000	$593,500	Deferred
Exterior paint	Energy	04/06/25	Q4 2027	$693,000	$427,339	Complete
Fence replacement	Site	09/20/25	Q1 2025	$195,000	$143,111	Bidding
Fence replacement	Interior	01/09/23	Q4 2026	$589,000	$373,933	Deferred
Roof replacement - Bldg A	Energy	08/23/26	Q3 2026	$473,000	$78,525	Approved
Security camera upgrade	Energy	08/10/25	Q3 2027	$797,000	$551,013	Bidding
Landscape / irrigation	Site	05/11/23	Q1 2027	$87,000	$35,603	Deferred
LED lighting retrofit	Interior	11/30/26	Q3 2026	$19,000	$17,401	Deferred
Sewer line repair	Building	01/17/26	Q3 2027	$186,000	$66,610	In progress
Water heater replacement	Life Safety	09/02/26	Q1 2027	$538,000	$531,369	Bidding
ADA compliance	Site	04/25/23	Q4 2027	$433,000	$407,401	Complete
Parking lot resurfacing	Energy	01/26/26	Q3 2026	$634,000	$374,237	Complete
Fence replacement	Energy	06/11/24	Q1 2025	$762,000	$470,932	Approved
Elevator modernization	Life Safety	07/16/24	Q4 2026	$553,000	$482,198	Deferred
Door hardware	Life Safety	04/20/26	Q3 2026	$328,000	$120,376	Bidding
LED lighting retrofit	Life Safety	09/20/26	Q1 2026	$384,000	$9,948	Complete
Exterior paint	Energy	10/06/25	Q3 2026	$699,000	$464,530	In progress
Parking lot resurfacing	Interior	10/11/24	Q1 2026	$272,000	$211,734	In progress
Pool resurfacing	Interior	06/12/25	Q3 2027	$898,000	$719,025	Deferred
Fire alarm panel upgrade	Site	02/17/23	Q2 2027	$91,000	$37,684	Approved
Signage / monument	Building	01/13/23	Q3 2027	$231,000	$109,829	Complete
Fence replacement	Interior	02/09/24	Q3 2025	$832,000	$406,447	In progress
Fire alarm panel upgrade	Interior	12/01/25	Q1 2025	$13,000	$3,915	Deferred
Door hardware	Building	08/02/24	Q4 2026	$759,000	$265,479	In progress
Amenity renovation	Building	07/04/25	Q2 2027	$766,000	$764,989	Deferred
Security camera upgrade	Site	08/19/23	Q3 2027	$618,000	$537,734	Complete
Water heater replacement	Energy	12/20/25	Q2 2027	$392,000	$346,156	In progress
Lobby renovation	Interior	11/16/23	Q1 2025	$137,000	$8,650	Bidding
Landscape / irrigation	Building	05/03/23	Q1 2025	$271,000	$126,976	Complete
Water heater replacement	Building	01/06/25	Q4 2025	$31,000	$30,924	Deferred
Elevator modernization	Energy	05/06/26	Q1 2026	$708,000	$195,114	Approved
LED lighting retrofit	Energy	01/29/26	Q4 2027	$319,000	$278,638	Complete
Fire alarm panel upgrade	Energy	04/10/23	Q2 2025	$19,000	$934	In progress
Landscape / irrigation	Building	01/11/24	Q4 2026	$782,000	$30,450	Deferred
Pool resurfacing	Energy	12/08/26	Q4 2026	$163,000	$45,586	Bidding
Amenity renovation	Building	11/02/23	Q4 2026	$666,000	$296,185	Complete
LED lighting retrofit	Life Safety	03/26/25	Q2 2027	$277,000	$236,327	Approved
Roof replacement - Bldg D	Site	09/26/24	Q4 2026	$369,000	$357,988	Deferred

Report generated 01/22/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Elevators were last modernized 7 years ago and are operating without deficiency. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 40 months.

ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $461,000. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 32 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months.

Investor Distributions

The business plan contemplates a hold period of 7 years with disposition upon achievement of target returns. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The facility is a purpose-built data center with 32 MW of critical IT load, N+1 power and cooling redundancy, and dual utility feeds. Carrier-neutral meet-me room supports multiple fiber providers.

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. On-site infrastructure includes diesel generators, UPS systems, CRAC units and a biometric-controlled security perimeter. Carrier-neutral meet-me room supports multiple fiber providers. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The facility is a purpose-built data center with 13 MW of critical IT load, N+1 power and cooling redundancy, and dual utility feeds. The business plan contemplates a hold period of 9 years with disposition upon achievement of target returns.

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 9 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $335,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $459,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Elevators were last modernized 8 years ago and are operating without deficiency. Electrical service is adequate for current demand; select panels are nearing the end of their useful life.

Investor Distributions

Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The business plan contemplates a hold period of 5 years with disposition upon achievement of target returns. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The facility is a purpose-built data center with 4 MW of critical IT load, N+1 power and cooling redundancy, and dual utility feeds.

Tenants are billed per kilowatt of contracted capacity with power pass-through at metered cost. The investment thesis is based on stabilizing occupancy, completing the capital plan and capturing rent growth to market. The business plan contemplates a hold period of 11 years with disposition upon achievement of target returns. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Projected levered IRR is 8.2% with an equity multiple of 1.46x over the hold period.

Recommendations

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $311,000. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 14 months. Elevators were last modernized 3 years ago and are operating without deficiency.

Elevators were last modernized 10 years ago and are operating without deficiency. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $124,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Domestic water piping is copper and PVC with no evidence of widespread leakage.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Elevator modernization	Life Safety	09/23/26	Q4 2025	$335,000	$169,225	Complete
Water heater replacement	Building	05/08/26	Q4 2026	$826,000	$637,824	Bidding
Exterior paint	Site	08/02/23	Q2 2027	$220,000	$151,023	Deferred
HVAC replacement	Life Safety	06/29/26	Q4 2026	$179,000	$46,616	Deferred
Pool resurfacing	Life Safety	10/17/25	Q2 2026	$740,000	$385,975	Complete
Exterior paint	Life Safety	09/24/26	Q2 2025	$493,000	$251,223	Complete
Unit interior upgrades	Interior	12/13/26	Q1 2026	$787,000	$709,745	In progress
Security camera upgrade	Energy	12/25/26	Q4 2025	$78,000	$2,821	Deferred
LED lighting retrofit	Building	11/18/25	Q1 2025	$316,000	$128,461	Deferred
Landscape / irrigation	Site	02/03/26	Q2 2027	$522,000	$418,217	Deferred
Elevator modernization	Energy	07/11/24	Q1 2025	$556,000	$344,736	Complete
Storefront glazing	Building	06/15/23	Q2 2025	$680,000	$212,968	Complete
LED lighting retrofit	Site	01/05/23	Q2 2026	$749,000	$178,282	Complete
Pool resurfacing	Life Safety	06/23/24	Q1 2025	$617,000	$524,127	Approved
Door hardware	Energy	11/10/24	Q1 2025	$249,000	$45,887	Deferred
LED lighting retrofit	Building	05/19/26	Q2 2026	$150,000	$92,395	In progress
Fence replacement	Building	03/21/24	Q4 2026	$762,000	$346,437	Approved
Signage / monument	Energy	08/17/24	Q4 2026	$824,000	$112,978	Bidding
Sewer line repair	Life Safety	01/23/26	Q3 2027	$804,000	$257,429	In progress
Roof replacement - Bldg C	Site	08/26/26	Q4 2026	$507,000	$385,629	Approved
Door hardware	Site	01/30/24	Q1 2027	$590,000	$298,473	Approved
HVAC replacement	Building	11/23/25	Q2 2027	$431,000	$242,083	Complete
Sewer line repair	Site	06/02/26	Q2 2027	$604,000	$385,527	Approved
Door hardware	Building	09/23/25	Q1 2025	$726,000	$403,840	Deferred
Fire alarm panel upgrade	Life Safety	12/29/23	Q4 2027	$213,000	$3,578	Complete
Signage / monument	Building	06/15/24	Q2 2025	$233,000	$238,784	Approved
Sewer line repair	Site	06/08/25	Q4 2025	$545,000	$238,151	Bidding
Fence replacement	Interior	05/09/25	Q3 2027	$298,000	$232,319	In progress
Parking lot resurfacing	Building	07/31/24	Q1 2027	$633,000	$33,420	Complete
Fence replacement	Life Safety	04/22/24	Q1 2025	$646,000	$332,883	Complete
Landscape / irrigation	Life Safety	01/08/26	Q2 2026	$511,000	$341,927	Bidding
HVAC replacement	Building	01/26/24	Q3 2025	$328,000	$308,734	Approved
ADA compliance	Life Safety	10/02/23	Q4 2025	$153,000	$77,218	Deferred
Signage / monument	Energy	07/15/25	Q3 2027	$34,000	$17,500	Complete
Exterior paint	Life Safety	01/16/25	Q3 2025	$132,000	$61,517	In progress
Roof replacement - Bldg C	Site	09/21/26	Q4 2027	$754,000	$525,131	Bidding
Fire alarm panel upgrade	Building	04/03/25	Q3 2026	$413,000	$227,754	Approved
Lobby renovation	Building	08/06/25	Q3 2026	$236,000	$225,059	Complete
HVAC replacement	Interior	04/11/23	Q3 2025	$131,000	$124,054	Bidding
Fence replacement	Building	08/08/26	Q2 2027	$344,000	$339,313	Complete
Signage / monument	Energy	11/28/24	Q4 2027	$859,000	$510,088	Complete

Report generated 01/22/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Deferred Maintenance

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 3 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $293,000. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 4 years ago and are operating without deficiency.

The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $247,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 25 months. Elevators were last modernized 10 years ago and are operating without deficiency.

Risk Considerations

Projected levered IRR is 13.0% with an equity multiple of 1.35x over the hold period. Tenants are billed per kilowatt of contracted capacity with power pass-through at metered cost. The business plan contemplates a hold period of 5 years with disposition upon achievement of target returns. Carrier-neutral meet-me room supports multiple fiber providers. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Leasing velocity improved during the period and management expects further upward pressure on in-place rents. The business plan contemplates a hold period of 12 years with disposition upon achievement of target returns. Carrier-neutral meet-me room supports multiple fiber providers. Projected levered IRR is 3.6% with an equity multiple of 1.46x over the hold period.

Observed Conditions

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 38 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $265,000.

Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage. Elevators were last modernized 4 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Business Plan Progress

Projected levered IRR is 13.1% with an equity multiple of 1.31x over the hold period. Leasing velocity improved during the period and management expects further upward pressure on in-place rents. Tenants are billed per kilowatt of contracted capacity with power pass-through at metered cost. The business plan contemplates a hold period of 3 years with disposition upon achievement of target returns. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions.

On-site infrastructure includes diesel generators, UPS systems, CRAC units and a biometric-controlled security perimeter. Distributions to investors for the quarter were paid at an annualized rate of 6.6% on contributed capital. Carrier-neutral meet-me room supports multiple fiber providers. Leasing velocity improved during the period and management expects further upward pressure on in-place rents.

Recommendations

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 40 months. The roofing system exhibits localized ponding and sealant deterioration; spot repairs are recommended within 12 months. ADA observations include non-compliant slopes at two accessible routes and signage at parking; cost to cure is estimated at $151,000. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Domestic water piping is copper and PVC with no evidence of widespread leakage.

Asphalt paving shows alligator cracking and should be sealcoated and restriped during the next 36 months. Electrical service is adequate for current demand; select panels are nearing the end of their useful life. Elevators were last modernized 12 years ago and are operating without deficiency. Windows and exterior doors are in fair condition; sealant replacement is recommended at selected locations.

Business Plan Progress

Tenants are billed per kilowatt of contracted capacity with power pass-through at metered cost. Projected levered IRR is 9.9% with an equity multiple of 1.8x over the hold period. The business plan contemplates a hold period of 5 years with disposition upon achievement of target returns. The facility is a purpose-built data center with 38 MW of critical IT load, N+1 power and cooling redundancy, and dual utility feeds. Key risks include interest rate exposure, tenant rollover, construction cost overruns and local supply additions. Carrier-neutral meet-me room supports multiple fiber providers.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Capital Project Schedule

Project	Category	Start	Completion	Budget	Spent to Date	Status
Fence replacement	Energy	11/18/25	Q4 2027	$323,000	$322,685	In progress
Elevator modernization	Building	10/11/24	Q2 2025	$369,000	$216,184	Deferred
Storefront glazing	Site	03/20/23	Q4 2025	$34,000	$20,683	In progress
Roof replacement - Bldg A	Life Safety	06/18/24	Q2 2025	$563,000	$321,285	Approved
Pool resurfacing	Interior	05/01/23	Q4 2027	$489,000	$148,229	Bidding
Storefront glazing	Life Safety	11/14/23	Q1 2027	$525,000	$534,491	Bidding
Door hardware	Building	01/15/25	Q4 2026	$533,000	$341,591	Complete
Roof replacement - Bldg D	Building	01/14/26	Q3 2025	$169,000	$37,350	Deferred
Fence replacement	Interior	03/11/23	Q1 2025	$503,000	$185,036	Bidding
Fence replacement	Energy	12/04/25	Q1 2027	$757,000	$305,887	Complete
Elevator modernization	Energy	07/26/23	Q2 2027	$481,000	$70,755	Bidding
Door hardware	Energy	06/29/26	Q3 2026	$236,000	$139,804	Deferred
Parking lot resurfacing	Building	07/20/25	Q2 2026	$115,000	$102,427	Bidding
Door hardware	Building	08/08/23	Q4 2026	$830,000	$57,955	Complete
Elevator modernization	Building	06/18/23	Q1 2027	$841,000	$265,265	Complete
Amenity renovation	Building	04/24/25	Q2 2026	$634,000	$421,097	Bidding
Door hardware	Life Safety	11/20/23	Q3 2026	$650,000	$109,494	Bidding
Exterior paint	Energy	02/19/23	Q3 2027	$744,000	$533,992	In progress
Pool resurfacing	Interior	08/26/23	Q2 2025	$558,000	$332,336	Complete
Sewer line repair	Life Safety	09/03/26	Q4 2025	$589,000	$284,910	In progress
Landscape / irrigation	Site	05/28/24	Q3 2027	$557,000	$352,858	Approved
ADA compliance	Interior	08/20/23	Q3 2025	$112,000	$89,958	Approved
Lobby renovation	Energy	07/31/24	Q2 2027	$824,000	$580,860	Deferred
ADA compliance	Life Safety	07/03/24	Q4 2026	$632,000	$187,945	Bidding
Door hardware	Interior	06/30/26	Q4 2027	$238,000	$178,132	In progress
LED lighting retrofit	Life Safety	12/05/23	Q2 2026	$875,000	$204,401	Bidding
Pool resurfacing	Life Safety	10/26/24	Q3 2026	$868,000	$462,126	Bidding
ADA compliance	Building	10/01/23	Q4 2025	$612,000	$520,889	In progress
Amenity renovation	Energy	02/09/23	Q3 2027	$118,000	$7,705	Complete
Lobby renovation	Interior	05/10/24	Q3 2027	$234,000	$108,783	In progress
Door hardware	Life Safety	08/30/26	Q2 2025	$184,000	$156,543	Deferred
Pool resurfacing	Interior	06/29/24	Q4 2026	$620,000	$465,397	Approved
Pool resurfacing	Interior	10/07/24	Q4 2027	$307,000	$28,321	Deferred
Security camera upgrade	Building	05/15/24	Q2 2027	$155,000	$30,526	Bidding
Unit interior upgrades	Life Safety	10/31/23	Q3 2025	$545,000	$226,940	Approved
Pool resurfacing	Life Safety	05/23/23	Q2 2025	$311,000	$186,920	Approved
Roof replacement - Bldg D	Site	08/19/25	Q4 2026	$541,000	$172,659	Approved
Parking lot resurfacing	Interior	03/09/24	Q1 2027	$281,000	$124,480	Deferred
Fire alarm panel upgrade	Life Safety	09/16/24	Q1 2026	$690,000	$634,200	Complete
Water heater replacement	Life Safety	10/25/24	Q1 2027	$699,000	$59,242	Deferred
Door hardware	Building	01/07/25	Q2 2025	$248,000	$52,521	Bidding
Exterior paint	Interior	03/20/25	Q4 2025	$421,000	$69,390	Deferred
Landscape / irrigation	Interior	01/18/25	Q4 2026	$151,000	$47,502	Complete

Report generated 01/22/2026. Figures are unaudited and subject to change.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only

Summary and Notes

Income and Expense Review

The going-in capitalization rate of 5.87% reflects the in-place income and the stabilized occupancy assumption. Net operating income is projected to grow at a compound annual rate of 4.5% over the hold period. Operating expenses totaled $228,000 or approximately 15.05 per square foot, with real estate taxes representing the largest line item. On-site infrastructure includes diesel generators, UPS systems, CRAC units and a biometric-controlled security perimeter.

Net operating income is projected to grow at a compound annual rate of 3.1% over the hold period. A reserve for replacements of $250 per unit has been underwritten in the cash flow below net operating income. Carrier-neutral meet-me room supports multiple fiber providers. Effective gross income for the trailing period was $47,000, representing a 13.0% increase over the prior year. Management fees are calculated at 7.7% of collected revenue and are included in operating expenses.

Property Operations

Collections for the period were 95.5% of billed charges, with bad debt of 6.2% of gross potential income. On-site staffing consists of a property manager, assistant manager, maintenance supervisor and 45 additional team members. Service requests are tracked through a work-order system with an average completion time of 15 hours. Tenants are billed per kilowatt of contracted capacity with power pass-through at metered cost.

Preventive maintenance schedules for HVAC, elevators and life-safety systems were completed on time during the period. Collections for the period were 89.2% of billed charges, with bad debt of 4.7% of gross potential income. On-site staffing consists of a property manager, assistant manager, maintenance supervisor and 33 additional team members. The facility is a purpose-built data center with 31 MW of critical IT load, N+1 power and cooling redundancy, and dual utility feeds. On-site infrastructure includes diesel generators, UPS systems, CRAC units and a biometric-controlled security perimeter.

FICTITIOUS SAMPLE DOCUMENT — all names, figures and entities are invented for classroom training use only