```
Sys.S = 3/2;
Sys.q = 2.008;
%Svs.A = ??:
Sys.Nucs = '29Si';
Sys.D = 34;
Sys.lwpp = [8 1];
Sys.DStrain=5;
Exp.Field = 370.78; % mT
Exp.mwRange=[10.2 10.6]; % GHz
Exp.nPoints=1024;
Exp.Harmonic=0;
Exp.Temperature=298;
Exp.CrystalOrientation = [0 0 0]*pi/180;
Opt.Transitions=[1 2: 3 4]:
```