


Rule #83 — Crossings: plate gets notch from stud — tool type drifts

Example: HG260002 | plan GF-RP-70.075 | frame R1 | stick T1

Crossings on plate from stud — position usually right, tool TYPE drifts on RP.


CODEC EMITS

(extra)
Detailer
doesn't
have these



DETAILER REF

(missing)
codec
should have
emitted these



Stick totals on this example:

- Matched ops: 0
- Extras (codec emits, Detailer doesn't): 22
- Missing (Detailer has, codec doesn't): 23

How to read:

- Top strip = ops the CODEC currently emits but Detailer's reference doesn't have (red = wrong-emit).
- Bottom strip = ops Detailer's reference has but the CODEC doesn't emit (red = miss).
- The yellow bar in the middle = the stick body, drawn to scale.
- Spans (Swage/LipNotch/InnerNotch) are coloured rectangles.
- Points (InnerDimple/Bolt/Web) are vertical lines + dots.