



DynaSaRR Medkit Bottom Motor Mount. CNCed I Required

Tolerance $\pm 1/64$ or $\pm .005$



