








FEATHER OFF
EN
GND
JP1: shunt ONLY
BATT
VSYS
GND
without charger
BATT
EN wire
OUT G IN
S9V11F5 soldered low
LIS3DH soldered low
bq24074 charger (optional)
soldered low
RACE-TRACKER ESP32 ROVER CARRIER rev C
ArduSimple: solder male headers underneath, plug in here
switch DOWN (5V IN, IOREF N/C)
USB-C
FEATHER display up, on stacking headers
USB-C


J1
J2
TP2
J5
J8
J3
J4
TP1
J11