

After execute the program this is the first screen that appears:

Here you must press 1 or 2 according to the query type, 1 for part number and 2 for reference, also you can press 9 to close the program.

After pressing 1 the screen below appears, and the cursor goes to the line below "P/N", then you must introduce the part number to find and press enter. After that you can go up and down with the up and down arrow keys of the keyboard.



For another query you must press 9, then introduce the query type and after, the part number or the reference, according to the query type, in the case of the photo below, the query type is by reference.



The photo below, show how the screen looks after introducing a part number or reference that can't be found, to get out of this, press 9

