ku name	product_category	measurement_type	cable_type
1098293 LaserCheck	hybrid meter and sensor combined	•	not applicable
1098297 FieldMate - Laser Power Meter	meter	laser power	not applicable
1098314 PM30	sensor	laser power	DB25 for use with a
1098329 PM2	sensor	laser power	DB25 for use with
1098336 PM3	sensor	laser power	DB25 for use with
1098341 PS19Q	sensor	laser power	DB25 for use with a
1098350 PS10	sensor	laser power	DB25 for use with a
1098398 PM150-50	sensor	laser power	DB25 for use with
1098400 PS10Q	sensor	laser power	DB25 for use with a
1098407 PM150	sensor	laser power	DB25 for use with a
1098412 PM150-50C	sensor	laser power	DB25 for use with a
1098413 PS19	sensor	laser power	DB25 for use with a
1098417 PM300F-50	sensor	laser power	DB25 for use with a
1098443 PM150-50XC	sensor	laser power	DB25 for use with a
1098455 PM150X	sensor	laser power	DB25 for use with a
1098457 PM2X	sensor	laser power	DB25 for use with
1098461 PM5K-100	sensor	laser power	DB25 for use with
1098472 PM200F-50	sensor	laser power	DB25 for use with
1098480 PM200F-19	sensor	laser power	DB25 for use with a
1098481 PM300F-50X	sensor	· ·	DB25 for use with a
		laser power	DB25 for use with a
1098490 PM1K-100	sensor	laser power	
1098498 PM30X	sensor	laser power	DB25 for use with
1098505 PM5K-200	sensor	laser power	DB25 for use with
1098506 PM3K-100	sensor	laser power	DB25 for use with
1098509 PM300F-19	sensor	laser power	DB25 for use with
1098579 FieldMaxII-TO - Laser Power Meter	meter	laser power	not applicable
1098580 FieldMaxII-TOP - Laser Power and Energy Meter	meter	laser power and ene	r _i not applicable
1110572 J-50MUV-248 with Diffuser	sensor	laser energy	DB25 for use with
1110573 J-50MB-HE Energy Sensor	sensor	laser energy	DB25 for use with
1110574 J-50MT-10KHZ Energy Sensor	sensor	laser energy	DB25 for use with
1110575 J-50MUV-193 with Diffuser	sensor	laser energy	DB25 for use with
1110576 J-50MB-LE Energy Sensor	sensor	laser energy	DB25 for use with
1110577 J-25MB-IR Energy Sensor	sensor	laser energy	DB25 for use with
1110741 J-25MUV-193 w/o Diffuser	sensor	laser energy	DB25 for use with
1110743 J-25MB-LE Energy Sensor	sensor	laser energy	DB25 for use with
1110744 J-50MB-YAG Energy Sensor	sensor	laser energy	DB25 for use with
1110745 J-25MUV-248 w/o Diffuser	sensor	laser energy	DB25 for use with
1110746 J-25MB-HE Energy Sensor	sensor	laser energy	DB25 for use with
1110747 J-25MT-10KHZ Energy Sensor	sensor	laser energy	DB25 for use with a
1110843 J-10MB-HE Energy Sensor	sensor	laser energy	DB25 for use with a
1110855 J-10MB-LE Energy Sensor	sensor		DB25 for use with a
		laser energy	DB25 for use with
1110856 J-10MT-10KHZ Energy Sensor	sensor	laser energy	
1113493 PM200F-50X	sensor	laser power	DB25 for use with
1115484 PM1KX	sensor	laser power	DB25 for use with
1140408 J-10Ge-LE Quantum Energy Sensor	sensor	laser energy	DB25 for use with
1140727 J-10Si-LE Quantum Energy Sensor	sensor	laser energy	DB25 for use with
1141474 PM300	sensor	laser power	DB25 for use with
1144701 J-50MB-YAG-1528 Energy Sensor	sensor	laser energy	DB25 for use with a
1146237 J-50MUV-193 w/o Diffuser	sensor	laser energy	DB25 for use with
1146243 J-50MUV-248 w/o Diffuser Energy Sensor	sensor	laser energy	DB25 for use with
1150146 J-10Si-HE Quantum Energy Sensor	sensor	laser energy	DB25 for use with
1151431 J-50MB-YAG-1535 Energy Sensor	sensor	laser energy	DB25 for use with a
1152086 PM1KX-100	sensor	laser power	DB25 for use with a
1155722 J-50MB-IR Energy Sensor	sensor	laser energy	DB25 for use with
1168337 PowerMax-USB UV/VIS Quantum Power Sensor	sensor	laser power	USB
1168343 PowerMax-USB PS19Q	sensor	laser power	USB
1168344 PowerMax-USB PM10-19C	sensor	laser power	USB
1168345 PowerMax-RS PM10-19C	sensor	laser power	RS-232
1168346 PowerMax-USB PM150-19C	sensor	laser power	USB
1168347 PowerMax-RS PM150-19C	sensor	laser power	RS-232
1168348 PowerMax-USB PM150-50C	sensor	laser power	USB
		•	RS-232
1168349 PowerMax-RS PM150-50C Power Sensor	sensor	laser power	
1174257 PowerMax-USB PM30	sensor	laser power	USB
1174258 PowerMax-RS PM30	sensor	laser power	RS-232
1174259 PowerMax-RS PM30X	sensor	laser power	RS-232
1174260 PowerMax-USB PS10	sensor	laser power	USB
1174261 PowerMax-USB PS19	sensor	laser power	USB

1174262 PowerMax-USB PM10	sensor	laser power	USB
1174263 PowerMax-USB PM3	sensor	laser power	USB
1174264 PowerMax-USB PM2	sensor	laser power	USB
1174267 PowerMax-RS PM1K-36C Power Sensor	sensor	laser power	RS-232
1174756 J-50MB-YAG-1561 Energy Sensor	sensor	laser energy	DB25 for use with a meter
1179504 PowerMax-RS PS19Q	sensor	laser power	RS-232
1184874 PowerMax-USB PM10X	sensor	laser power	USB
1191427 EnergyMax-RS J-10SI-HE Energy Sensor	sensor	laser energy	RS-232
1191428 EnergyMax-RS J-10MB-LE Energy Sensor	sensor	laser energy	RS-232
1191429 EnergyMax-RS J-10MB-HE Energy Sensor	sensor	laser energy	RS-232
1191430 EnergyMax-RS J-50MB-YAG Energy Sensor	sensor	laser energy	RS-232
1191431 EnergyMax-RS J-25MB-LE Energy Sensor	sensor	laser energy	RS-232
1191432 EnergyMax-RS J-50MB-HE Energy Sensor	sensor	laser energy	RS-232
1191433 EnergyMax-RS J-50MT-10KHZ Energy Sensor	sensor	laser energy	RS-232 USB
1191434 EnergyMax-USB J-10SI-HE Energy Sensor 1191435 EnergyMax-USB J-10MB-LE Energy Sensor	sensor	laser energy	USB
1191436 EnergyMax-USB J-10MB-HE Energy Sensor	sensor sensor	laser energy laser energy	USB
1191437 EnergyMax-USB J-50MB-YAG Energy Sensor	sensor	laser energy	USB
1191438 EnergyMax-USB J-50MB-YAG-1535 Energy Sensor	sensor	laser energy	USB
1191439 EnergyMax-USB J-50MB-YAG-1528 Energy Sensor	sensor	laser energy	USB
1191440 EnergyMax-USB J-50MB-IR Energy Sensor	sensor	laser energy	USB
1191441 EnergyMax-USB J-25MB-LE Energy Sensor	sensor	laser energy	USB
1191442 EnergyMax-USB J-25MB-HE Energy Sensor	sensor	laser energy	USB
1191443 EnergyMax-USB J-50MB-LE Energy Sensor	sensor	laser energy	USB
1191444 EnergyMax-USB J-50MB-HE Energy Sensor	sensor	laser energy	USB
1191445 EnergyMax-USB J-10MT-10KHZ Energy Sensor	sensor	laser energy	USB
1191446 EnergyMax-USB J-25MT-10KHZ Energy Sensor	sensor	laser energy	USB
1191447 EnergyMax-USB J-50MT-10KHZ Energy Sensor	sensor	laser energy	USB
1191448 EnergyMax-USB J-25MUV-193 w/o Diffuser Energy Sensor	sensor	laser energy	USB
1191449 EnergyMax-USB J-50MUV-248 with Diffuser Energy Sensor	sensor	laser energy	USB
1214871 PowerMax-RS PM1KX-100	sensor	laser power	RS-232
1219962 EnergyMax-RS J-50MB-YAG-1535 Energy Sensor	sensor	laser energy	RS-232
1223336 PowerMax-USB PM150-50	sensor	laser power	USB
1224012 BeamMaster-USB System BM-3 (UV)	beam diagnostics system	laser beam profile a	ınınot applicable
1224014 BeamMaster-USB System BM-7 (UV)	beam diagnostics system	laser beam profile an not applicable	
1224016 BeamMaster-USB System BM-3 (InGaAs)	beam diagnostics system	laser beam profile aninot applicable	
1224018 BeamMaster-USB System BM-7 (InGaAs 3mm)	beam diagnostics system	laser beam profile an not applicable	
1224020 BeamMaster-USB System BM-7 (InGaAs 5mm)	beam diagnostics system	laser beam profile a	ininot applicable
1230323 PowerMax-RS PM2X	sensor	laser power	RS-232
1235755 PowerMax-USB PM5K-100	sensor	laser power	USB
1236447 PowerMax-RS PM10X	sensor	laser power	RS-232
1257617 PowerMax-USB PM2X	sensor	laser power	USB
1263294 PowerMax-USB PM30X	sensor	laser power	USB
1268881 LabMax-Pro SSIM - Laser Power and Energy Meter	meter	laser power and en	
1282868 LaserCam HR II - 1/2" USB Camera System	beam diagnostics system	laser beam profile aninot applicable	
1282870 LaserCam HR II - 2/3" USB Camera System	beam diagnostics system	laser beam profile a	• •
1286950 EnergyMax-USB J-10Ge-LE Energy Sensor	sensor	laser energy	USB
1287077 PowerMax-USB PS10Q 1288940 PowerMax-USB PM100-19C	sensor	laser power	USB USB
1288992 PowerMax-RS PS10Q	sensor	laser power	RS-232
1289935 EnergyMax-USB J-50MUV-193 w/o Diffuser Energy Sensor	sensor sensor	laser power laser energy	USB
1299161 PowerMax-USB UV/VIS Wand Power Sensor	sensor	laser power	USB
1305568 PowerMax-RS PM150-50XC	sensor	laser power	RS-232
1317151 PowerMax-RS PM150-50	sensor	laser power	RS-232
1360550 LaserCam-HR II UV 2/3" USB Camera System	beam diagnostics system	laser beam profile a	
1402728 PM6K+ Laser Power Sensor	sensor	laser power	DB25 for use with a meter
1402729 PowerMax-USB PM6K+ Power Sensor	sensor	laser power	USB
1402730 PowerMax-RS PM6K+ Power Sensor	sensor	laser power	RS-232
1409621 PM1K+ Laser Power Sensor	sensor	laser power	DB25 for use with a meter
1409622 PowerMax-USB PM1K+ Power Sensor	sensor	laser power	USB
1409623 PowerMax-RS PM1K+ Power Sensor	sensor	laser power	RS-232
1409627 PM3K+ Laser Power Sensor	sensor	laser power	DB25 for use with a meter
1409628 PowerMax-USB PM3K+ Power Sensor	sensor	laser power	USB
1409629 PowerMax-RS PM3K+ Power Sensor	sensor	laser power	RS-232
2256258 LabMax Touch - Laser Power and Energy Meter	meter	laser power and enerinot applicable	
2256259 LabMax Touch Pro - Laser Power and Energy Meter	meter	laser power and en	
1097901 PM10	sensor	laser power	DB25 for use with a meter