Date: 2017/05/09

Student ID:

Name:

Given the following sequence of instructions, if there's full forwarding in the pipelined processor, indicate hazards and insert "nop" (no operation) instructions to eliminate them.

or r1, r2, r3

or r1, r1, r2

or r2, r1, r4

IF ID EX MEM WB

IF ID EX MEM WB

W/ALU-ALU

W/ MEM-ALU

Date: 2017/05/09

Student ID:

Name:

Given the following sequence of instructions, if there's no forwarding in the pipelined processor, indicate hazards and insert "nop" (no operation) instructions to eliminate them.

IF ID EX MEM WB

O O IT ID EX MEM MB