## **DGM Aircraft / Justice Air Maintenance**

9100 Republic Airport Farmingdale, NY 11735 US +16312704144 diana@justiceair.com





## **INVOICE**

 BILL TO
 INVOICE
 2276

 Avi
 DATE
 08/27/2024

 Aspire Aviation
 TERMS
 Net 10

 1100 New Highway
 DUE DATE
 09/06/2024

 Farmingdale, NY 11735

ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
Piper 50 HR Inspection	N433SP - 50 HR Inspection.	1	250.00	250.00
Flight School Labor Rate	<ul> <li>N433SP</li> <li>Pilot reported landing light inop during pre flight inspection.     During troubleshoot discovered blow landing light bulb.</li> <li>Removed and replaced landing light bulb with new IAW AMM.</li> <li>Ops check OK, landing light illuminates. (1.0 hr labor)</li> <li>During inspection found bold spot on LH main landing gear tire.     Removed and replaced LH MLG tire and tube with new IAW AMM. (1.0 hr labor)</li> <li>Right hand main landing tire worn beyond limits.     Removed and replaced RH MLG tire and tube with new IAW AMM. (1.0 hr labor)</li> <li>Left hand strobe light inop needs to be replace.     Troubleshot and found strobe power supply inop. Removed and replaced strobe power supply for new model. (2.0 hr labor)</li> <li>Customer reported excessive deviation on directional gyro.     Checked vacuum system connections and found ok.</li> <li>Performed run up and taxi and unable to duplicate. (1.0 hr labor)</li> <li>Customer reported magnetic compass is off.     Unable to check on ground. Informed owner that a compass swing is needed to verify and recommend avionics shop. (No additional labor charge.)</li> <li>AMP meter requires installation with new unit.     Removed serviceable (loaner instrument) and replaced with new vacuum and amp gauge. (1.0 hr labor)</li> </ul>	7	95.00	665.00
Parts	Phillips 20W-50	7	12.00	84.00
Parts	Tempest 110 oil filter	1	40.00	40.00
Parts	Oil analysis kit	1	30.31	30.31
Parts	Air Hawk Tire	2	143.75	287.50
Parts	Leakguard inner tube	2	124.02	248.04
Parts	Bulb	1	14.89	14.89

Parts	Cotter pin	2	0.25	0.50
Parts	Whelen power supply	1	960.52	960.52
Parts	Vacuum/amp indicator	1	1,236.25	1,236.25
Parts	Vacuum/pump core charge (Powerpacks plus)	1	1,500.00	1,500.00
Parts	Inspection for vacuum amp gauge (not repairable)	1	46.00	46.00
Shipping and Freight Charges	Shipping for amp out for inspection	1	18.18	18.18
Shipping and Freight Charges	Shipping for amp core back to DGM	1	20.50	20.50
Shipping and Freight Charges	Shipping for amp gauge	1	48.21	48.21
Shipping and Freight Charges	Shipping core back to vendor	1	23.00	23.00
Shop Supplies	Consumables & shop supplies	1	25.00	25.00

 <sup>-</sup> Vacuum/Amp core was sent to Powerpacks plus for second evaluation.
 If the core Is repairable they will refund the core charge.
 WO# 887 & 905

\$5,497.90