Preliminary Invoice



8100 Republic Airport Farmingdale, NY 11735 United States March 25, 2025

Telephone: 631-756-5500 Fax: Maint@ventura.aero

Bill To: Aspire Aviation LLC

1100 New Hwy

Farmingdale, NY 11735

1.000000 USD

INVOICE SUMMARY FOR WORK ORDER NUMBER: NY1695

United States

Invoice Number: INV25-00118

Invoice Date: 03/24/2025

Account Code: ASPIRE AVIATION LLC

P.O. Number:

Job Number:

Registration Number: N9863L

Payment Type: Cash

Exchange Rate:

Payment Terms:

	Time & Materials	Flat Rate	Total
Labor:	504.00 USD		504.00 USD
Parts:	119.94 USD		119.94 USD
Total:	623.94 USD	0.00 USD	623.94 USD
Subtotal:			623.94 USD

Total: 623.94 USD





8100 Republic Airport Farmingdale, NY 11735 **United States**

March 25, 2025

Telephone: 631-756-5500 Fax: Maint@ventura.aero

WO #: NY1695 Bill To: Aspire Aviation LLC Invoice Number: INV25-00118

Item: 1 Airframe Part/Model #: 172P

Item Serial Number:

Registration Number: N9863L Aircraft Serial Number: 17276641

1.1 Discrepancy: Oil And Filter Change

Resolution: Oil changed and refilled with 7 Qts of 20W-50w Phillips 66 X/C. Filter changed with new P/N: AA48110-2. Leak check good.

	Time & Materials	Flat Rate	I Otal
Labor:	218.40 USD		218.40 USD
Parts:	119.94 USD		119.94 USD
Total:	338 34 USD	0.00 USD	338 34 USD

Parts:

Ref. No.	Part number	Description	Quantity	Sell price	Extended
1.1 #1	AA48110-2	Oil Filter - Tempest	1.00	46.65 USD	46.65 USD
1.1 #2	20W-50	OIL - PHILLIPS 66 X/C Aviation SAE 20W-50	7.00	10.47 USD	73.29 USD

Discrepancy: 1.2 Pilot side headphone jack intermittent

Resolution: Repaired multiple broken wire son Pilot Mic and Phone jack. Ground test good.

	Time & Materials	Flat Rate	lotai
Labor:	285.60 USD		285.60 USD
Total:	285.60 USD	0.00 USD	285.60 USD